OMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1272P

MAKE/REG 26.07.2017

TOYOTA PRIUS G4

22.06.2023

CHIANG/INCOME

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER CLIPS		
1	REAR BUMPER		\$503.04
1	REAR BUMPER RETAINER LH		\$112.70
10	REAR BUMPER CLIPS	\$2.20	\$22.00
1	REAR BUMPER LOWER COVER		\$654.96
1	REAR BUMPER LOWER SIDE COVER LH		\$232.00
1	TAIL LAMP UPPER LH	1750	\$557.90
1	TAIL LAMP LOWER LH		\$570.00
	SUB TOTAL	1312.50	\$2,652.60
	25.00%		\$663.15
	DISCOUNTED TOTAL		\$1,989.45
1	REAR REVERESE SENSOR	nu	メ \$135.70 \$135.7 0
ļ	Labour Charge Panel Beating	9	5° \$900.00
	pray Painting Charge	130 29	\$600.00
1	ruff Kote	630	×ng \$60.00
IR	emove and Refix Reverse Sensor	1942.50	\$60.00
	TOTAL LABOUR	4/5/1550	\$1,620.00
	ESTIMATE TOTAL	1942.50 61591550 2days	\$3,745.1
Α		*	

Tought 974 (941)

Wp) 17/6/73 Closon

22days

Els Newy affarrepair

faufth c//hunts.um

L K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
 Parts prices are subject to confirmation

 - * Third narty survey is on a "Without Prejudice" basis
 - a lan degai modification(s) is allowed
 - Cappir hentary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sonature: