

ASS. REC. BY: Marcus

REF:

CS / C7 / 2300 6521 / UVP3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: S/LV 2410Rat Workshop m/s Zoomof _____
Insured: SMS 811G

Policy No. _____

Claims No. SNM23D204509

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 854k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1766
Vehicle: IN / OUTDate: _____ Person Contacted: 474 829966Veh No: SKV 2410R Yr Regn: 31/08/15
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Bmw 3.8; c.c 1499Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 99188 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA8E32040K497610Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/50 R17BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/05/23 D.O.I. 28/06/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S Frt
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 18k.24/7/23 4/5 \$ 3900 in Bond Elin (red 11,302.36, 74%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 24/7/23-typistDays Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

____ S + RS, ____ SI

Photos

Others

Report Format : EzclaimsLump Sum H.B.I. (\$ 3900)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	176B
Vehicle Details	
Vehicle No.:	SKV2410R
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jun 2023
Vehicle Make:	B.M.W.
Vehicle Model:	318I SEDAN LED NAV
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	F9931203B38B15A
Chassis No.:	WBA8E32040K497610
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,993.00
Original Registration Date:	31 Aug 2015
First Registration Date:	31 Aug 2015
Transfer Count:	1
Actual ARF Paid:	\$28,991.00 14995
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2025
PARF Rebate Amount:	\$17,394.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,885.00
COE Rebate Amount:	\$12,572.00
Total Rebate Amount:	\$29,966.00

The information contained herein is correct as at 28 Jun 2023

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment. Loan by GV
Cars Financing at 3.28% p.a.
Low Interest Rate
GV Automobile Centre StarAd



Sort by results/page

4 vehicles



[Advanced Search](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection

BMW 318

Any

Any

2015

Any

Any

Any

Available



BMW 3 Series 318i Sport

\$55,800

\$19,090 /yr

31-Aug-2015

1,499 cc

128,300 km

Luxury

Available

Flawless inside out, immaculate paintwork! Impeccably maintained, hand wash only weekly by fervent owner. Ex-premium auto preown...

Car Buyers Automotive Pte Ltd

Posted: 26-Jun-2023

PREMIUM AD



BMW 3 Series 318i Sport

\$65,000

\$23,070 /yr

31-Aug-2015

1,499 cc

150,000 km

Luxury

Available

Beautiful crystal blue paintwork done in March 23. M3 bodykit with rear spoiler. Full servicing history available with invoice. All wear and...

Posted: 21-Jun-2023



BMW 3 Series 318i Sport

\$57,800

\$18,240 /yr

27-Oct-2015

1,499 cc

125,000 km

Luxury

Available

PML Unit, Well Taken Care Of And Serviced At Agent Performance Motors. Servicing Records Available In BMW iDrive System. Guarante...

Posted: 10-Jun-2023

DIRECT OWNER



BMW 3 Series 318i

\$63,800

\$20,670 /yr

27-Nov-2015

1,499 cc

135,000 km

Luxury

Available

Pristine condition! 100% loan available from 2.78% per annum! 1 to 1 exchange without cash top up! Hurry and call our friendly sales a...

Platinum Motoring

Posted: 04-Jun-2023

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

results/page

Buy / Rent Cars

[New Cars For Sale](#)

[Used Cars For Sale](#)

[Cars For Rent](#)

[Sell Your Car](#)

[Post an Ad](#)

[Compare](#)



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17 July 2023

Not Authorized
her

28/6/23

1/5 \$3900/

3 days

REG NO.: SKV 2410 R

MAKE/MODEL: BMW 318i

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front headlamp -RH <i>scr/one</i>	3,142.25
1	Front headlamp lower bracket <i>11</i>	113.00 X
1	Front bumper <i>Deep cut/Torn</i>	1,653.55
1	Front bumper fog lamp <i>11</i>	471.40 X
1	Front bumper fog lamp cover <i>11</i>	192.00 X
1	Front bumper inner sponge <i>11</i>	165.00 X
1	Front bumper side chrome moulding <i>11</i>	176.25 X
1	Front bumper logo <i>11</i>	59.00 X
1	Front bumper reinforcement <i>11</i>	726.00 X
1	Front bumper side retainer <i>11</i>	136.20 X
1	Front bumper top rubber seal <i>11</i>	90.00 X
1	Front fender -LH <i>R</i>	933.00 X
1	Front fender inner shield <i>11</i>	132.50 X
1	Front wheel rim <i>11</i>	1,274.70 X
1	Front wheel hub with bearing <i>11</i>	450.00 X
1	Front shock absorber <i>11</i>	585.00 X
1	Front knuckle arm <i>11</i>	570.00 X
1	Front lower arm <i>11</i>	380.00 X
		\$ 11,249.85
	Less 5%	\$ 562.49
		\$ 10,687.36

SPECIAL NETT ITEMS

1	Front bumper clip (1 set) <i>her</i>	\$ 60.00 40
1	Front fender inner shield clip (1 set) <i>11</i>	\$ 65.00 X
1	Front tyre <i>11</i>	\$ 600.00 X
		\$ 725.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	To remove and refit front undercarriage.	\$ 11 250.00 X
3	To conduct wheel alignment.	\$ 11 180.00 X
4	To apply undercoating.	\$ 11 180.00 X
5	Panel beating.	\$ 1,600.00 300
6	To re-spray painting on the affected areas.	\$ 1,500.00 400
		\$ 3,790.00

GRAND TOTAL :

\$ 15,202.36