



HKL LIM TEAM MOTORSPORT PTE LTD

UEN: 202218929Z

Blk 1008 #01-24 Bukit Merah Lane 3, Singapore 159722.

Tel: 6275 6656 Email: hklteam@gmail.com

FBK2605K

1	FRONT FORK ASSY LH/RH	\$700
2	FRONT FORK UNDER BRACKET	\$450
3	STEERING CONE BEARING	\$150
4	BODY FRAME ALIGNMENT	\$750
5	FRONT FENDER	\$190
6	HEAD COWLING	\$480
7	FRONT SIGNAL LH/RH	\$240
8	HANDLE BAR	\$240
9	HANDLE BAR BALANCER RH	\$30
10	BRAKE LEVER RH	\$60
11	SIDE MIRROR RH	\$90
12	LOWER COWLING RH	\$160
13	FRONT FOOT REST RH PANEL	\$190
14	TAIL LIGHT	\$250
15	REAR WHEEL RIM	\$550
16	TAILBOARD LH/RH	\$480
17	REAR NO PLATE	\$20
18	REAR NO PLATE LIGHT	\$45
19	LOWER CENTER PANEL	\$120
20	TOP BOX	\$180
21	TAIL PANEL TOP	\$150
22	TAIL PANEL BOTTOM	\$160
23	REAR FENDER	\$98
24	REAR WHEEL SHAFT	\$320
25	REAR WHEEL BEARING \$60X2	\$120
26	REAR WHEEL OIL SEAL	\$20
27	GEAR BOX COVER GASKET	\$35
28	EXHAUST HEADER	\$190
29	EXHAUST HEADER GASKET	\$15
30	EXHAUST MUFFLER	\$1,800
31	EXHAUST MUFFLER COVER	\$150
32	EXHAUST MUFFLER END CAP	\$80
33	EXHAUST MUFFLER GUARD	\$45
34	EXHAUST HEADER GUARD	\$45
35	EXHAUST MUFFLER GASKET	\$35
36	REAR SUSPENSION LH/RH	\$400

37	REAR BRAKE DISC	\$220
38	ENGINE MOUTING BRACKET	\$220
39	REAR SUSPENSION BRACKET	\$250
40	TOWING	\$40
41	LABOUR	\$780

TOTAL AMOUNT:	\$10,548
----------------------	-----------------

