

TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

SMG 973 B

Your ref:

SMK 5718 T

27 June 2023

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : MOHAMED SHARIL BIN SATAR

VEHICLE NUMBER : SMG 973 B

YOUR INSURED VEHICLE NUMBER : SMK 5718 T

ACCIDENT ON 19 APR 2023 AT ABOUT 04:15 HOURS

ALONG JLN SULTAN ISKANDAR CIQ JB - SG, KIM TENG PARK 80300 JOHOR BAHRU MALAYSIA

We refer to your email / fax dated **27 June 2023** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-17

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: