



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD
10 EUNOS ROAD 8
SINGAPORE POST CENTRE #09-04A
SINGAPORE 408600

Ref: CS/ICS23006535/y3

Date: 28/06/2023

Code: ICS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBG 1145Z
Policy No.	MCV23B00006900	Coverage (\$)	0.00
Claim No.	DMCV2300041H/ST	Excess (\$)	600.00
Assign From	SHARON TAN	Assign Date	28/06/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	21/06/2023	Inspection Date	30/06/2023
Survey held at	1 Defu Lane 6, 539365 Defu Lane		
Repairer	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM)		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.