

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/1CS23006535/Uny3

## ASSIGNMENT

Front: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBG 11452

at Workshop m/s

AIM

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

834k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4  
20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

37302

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 11952

Veh No:

GBG 11452

Yr Regn:

31/05/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

NISSAN NV200

C.C

1461

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

129220

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSKYBAM 2020143749

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/06/23

D.O.I.

5/7/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

dnt nls

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/7/23

4/582300 informed kelvin (Ref 4455, 667.)

Date/Time, File Pass to?

☐

Preli. Report

1) 27/7/23 typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format :

MER-00

Lump Sum / I.B.I. (\$

2300

TOTAL

## Automobile Integrated Management Pte Ltd (Co.Reg.No:201605297G)

1 Defu Lane 6

Singapore 539365

Tel: 91198371 Email: automim.claim@gmail.com

INSURER:

ECICS Limited (HQ)

## PARTICULARS OF CLAIM

|                               |                                               |                       |                   |
|-------------------------------|-----------------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                               | Ref. No:              | AC2023025/OD      |
| Policy No:                    | MCV23B00006900                                | Date of Loss:         | 21/06/2023        |
| Vehicle Reg. No.:             | GBG1145Z                                      | Driveable?            |                   |
| Driver Age/Info:              |                                               | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                            | Third Party Involved? | YES               |
| Insured/Claimant:             | SGPETSHOP                                     | Contact No:           | +6593877877       |
| Make/Model:                   | NISSAN NV200, 1.5 (M)                         | Vehicle Reg. Date:    | 31/05/2017        |
| Vehicle Colour:               | BLUE                                          | Chassis No:           | VSKYBAM20Z0143749 |
| Engine No:                    | K9KC400D057001                                |                       |                   |
| Odometer:                     | 128078 KM                                     |                       |                   |
| Paint Type:                   |                                               |                       |                   |
| Total Loss?                   | NO                                            |                       |                   |
| Est. Duration of Repair (day) | 5                                             |                       |                   |
| Present Location:             | AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) |                       |                   |

## COST OF CLAIMS

|                         | Amount          |
|-------------------------|-----------------|
| Parts                   | 3,355.00        |
| Miscellaneous Items     | 0.00            |
| Labour                  | 3,400.00        |
| Paintwork Labour        | 0.00            |
| Towing                  | 0.00            |
| <b>Gross Total (\$)</b> | <b>6,755.00</b> |
| <b>+ GST 8.00% (\$)</b> | <b>540.40</b>   |
| <b>Nett Amount (\$)</b> | <b>7,295.40</b> |

This claim is handled by: OPSTEAM1

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

not Authorised  
 Marcus Lee  
 5/7/23  
 2/5 \$2300  
 cheque after 4 days  
 4 days  
 excess \$600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**REPAIR DETAILS****Reference**

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 28 Jun 2023)                                                                                                                                             |
| <b>Parts:</b>        | N/A NISSAN NV200 1.5 (M) (Model not available in database)                                                                                                                   |
| <b>Labour:</b>       | Repairer's (Price-denominated Standard List)                                                                                                                                 |
| <b>Print Code:</b>   | Automobile Integrated Management Pte Ltd/GBG1145Z/28/06/2023 13:04                                                                                                           |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

**Estimates on Parts**

| No.                                 | Qty | Part No. | Particulars                           | %Disc | %Depr | Amount      |
|-------------------------------------|-----|----------|---------------------------------------|-------|-------|-------------|
| 1                                   | 1   |          | *Front bumper                         | 0.00  | DJS 0 | *340.00 F ✓ |
| 2                                   | 10  |          | *FRONT BUMPER CLIPS (SN)              | 0.00  | neu 0 | *30.00 F ✓  |
| 3                                   | 1   |          | *Front bumper tow cover               | 0.00  | 11 0  | *30.00 F X  |
| 4                                   | 1   |          | *FRONT BUMPER FOG LAMP (24) ALS       | 0.00  | 11 0  | *240.00 F X |
| 5                                   | 1   |          | *FRONT BUMPER SIDE RETAINER ALS       | 0.00  | one 0 | *30.00 F ✓  |
| 6                                   | 1   |          | *FRONT BUMPER SPONGE                  | 0.00  | 11 0  | *390.00 F X |
| 7                                   | 1   |          | *FRONT BUMPER REINFORCEMENT           | 0.00  | 11 0  | *420.00 F X |
| 8                                   | 1   |          | *FRONT FENDER ALS                     | 0.00  | Sub 0 | *300.00 F ✓ |
| 9                                   | 1   |          | *FRONT FENDER INNER COWLING ALS       | 0.00  | 11 0  | *100.00 F ✓ |
| 10                                  | 10  |          | *FRONT FENDER INNER COWLING CLIPS ALS | 0.00  | 11 0  | *30.00 F ✓  |
| 11                                  | 1   |          | *BONNET                               | 0.00  | 11 0  | *500.00 F X |
| 12                                  | 1   |          | *HEADLAMP ALS                         | 0.00  | 11 0  | *300.00 F ✓ |
| 13                                  | 1   |          | *HEADLAMP BRACKET ALS                 | 0.00  | one 0 | *60.00 F ✓  |
| 14                                  | 1   |          | *HEADLAMP OUTER GARNISH ALS           | 0.00  | 11 0  | *90.00 F X  |
| 15                                  | 1   |          | *FRONT BUMPER SIDE COVER TOP ALS      | 0.00  | 11 0  | *190.00 F ✓ |
| Sub Total (\$\$)                    |     |          |                                       |       |       | 3,050.00    |
| + Margin on L,N Items 10.00% (\$\$) |     |          |                                       |       |       | 305.00      |
| Total Parts (\$\$)                  |     |          |                                       |       |       | 3,355.00    |

F=Franchise part.

Automobile Integrated Management Pte Ltd/GBG1145Z/28/06/2023 13:04. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 FENDER GLASS SEALANT

11

- X

Sub Total (S\$)

0.00

## Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 Remove, refix of parts and panel beating.

New

750

1,500.00

2 Spraypaint

New

800

1,500.00

3 Wiring

New

20

120.00

4 Rust proof coating

New

112 X

180.00

5 Fender glass

New

11 X

100.00

Gross Labour Cost (S\$)

3,400.00

Automobile Integrated Management Pte Ltd/GBG1145Z/28/06/2023 13:04. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

P-1380  
102  
1518  
1370  
2888  
214  
2310