

ASS. REC. BY:

REF:

MSG/ 23006540/K943

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

Optima

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

\$ 228K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1.6%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNK 1455P Yr Regn: 031 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tesla Model 3 C.C. —

Colour:

M-P White

A/C: Insured / Std / NI / NA

Sp. Reading

5349

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LRW3F7F S0PC 799295

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

235/45ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

28/6/23

D.O.I.

3/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

01/5/24

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/7 21 Pm @ 1300h. Curb (red @ 7669.64, 67%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Report Format :

MER-TP

Lump Sum / LB.T: (\$

1300

Date: 28/06/2023

Vehicle No: SNK1455R

Model: TESLA MODEL 3 RWD

Chassis: LRW3F7FS0PC799295-2023

Reg.Year: 2023

Third Party Insurer: MSIG

Third Party Veh No: SGQ8687T

Date of Accident: 28/06/2023

Estimator: TING AN

Surveyor:

*Not withonw  
Primary B & pain  
4 day  
L1 Imp & 130 ch*

## ESTIMATE

| NO.         | DESCRIPTION                             | QTY | UNIT S\$ | AMOUNT S\$           |
|-------------|-----------------------------------------|-----|----------|----------------------|
| 1           | FRONT FENDER RH                         | 1   |          | <i>Rz</i> \$448.60   |
| 2           | FRONT FENDER INNER SHIELD RH            | 1   |          | <i>in</i> \$116.82   |
| 3           | FRONT FENDER SIGNAL LAMP WITH CAMERA RH | 1   |          | <i>in</i> \$196.26   |
| 4           | FRONT DOOR RH                           | 1   |          | <i>Rz</i> \$1,009.35 |
| 5           | FRONT DOOR WEATHERSTRIP RH              | 1   |          | <i>in</i> \$88.79    |
| 6           | SIDE SKIRT RH                           | 1   |          | <i>in</i> \$448.60   |
| 7           | FRONT SIDE MIRROR COVER RH              | 1   |          | <i>in</i> \$46.73    |
| SUB TOTAL   |                                         |     |          | \$2,355.15           |
| LESS 10%    |                                         |     |          | -\$235.52            |
| PARTS TOTAL |                                         |     |          | \$2,119.64           |

| NO.       | SPECIAL NETT                       | QTY | UNIT S\$ | AMOUNT S\$        |
|-----------|------------------------------------|-----|----------|-------------------|
| 1         | FRONT FENDER INNER SHEILD CLIPS RH | 1   |          | <i>in</i> \$40.00 |
| 2         | FRONT DOOR INNER TRIM BOARD CLIPS  | 1   |          | <i>in</i> \$50.00 |
| S/N TOTAL |                                    |     |          | \$90.00           |

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

*400*  
\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT FENDER RH, FRONT DOOR RH, SIDE SKIRT RH.

*650*  
\$700.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

*nn* \$120.00 X

#### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





Date: 28/06/2023  
 Vehicle No: SNK1455R  
 Model: TESLA MODEL 3 RWD  
 Chassis: LRW3F7FS0PC799295-2023  
 Reg.Year: 2023

Third Party Insurer: MSIG  
 Third Party Veh No: SGQ8687T  
 Date of Accident: 28/06/2023  
 Estimator: TING AN  
 Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 309

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 201

LABOUR TOTAL \$1,760.00

TING AN

TOTAL \$3,969.64

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

|                               |                                |  |
|-------------------------------|--------------------------------|--|
| Vehicle Owner Particulars     |                                |  |
| Owner ID Type:                | Singapore NRIC                 |  |
| Owner ID:                     | 580G                           |  |
| Vehicle Details               |                                |  |
| Vehicle No.:                  | SNK1455R                       |  |
| Vehicle to be Exported:       | No                             |  |
| Intended Deregistration Date: | 30 Jun 2023                    |  |
| Vehicle Make:                 | TESLA                          |  |
| Vehicle Model:                | MODEL 3 RWD                    |  |
| Primary Colour:               | White                          |  |
| Manufacturing Year:           | 2023                           |  |
| Engine No.:                   | -                              |  |
| Chassis No.:                  | LRW3F7FS0PC799295              |  |
| Maximum Power Output:         | 208.0 kW (278 bhp)             |  |
| Open Market Value:            | \$58,100.00                    |  |
| Original Registration Date:   | 23 Mar 2023                    |  |
| First Registration Date:      | 23 Mar 2023                    |  |
| Transfer Count:               | 0                              |  |
| Actual ARF Paid:              | \$31,580.00                    |  |
| Intended PARF Rebate Details  |                                |  |
| PARF Eligibility:             | Yes                            |  |
| PARF Eligibility Expiry Date: | 22 Mar 2033                    |  |
| PARF Rebate Amount:           | \$23,685.00                    |  |
| Intended COE Rebate Details   |                                |  |
| COE Expiry Date:              | 22 Mar 2033                    |  |
| COE Category:                 | B - Car-Details at OneMotoring |  |
| COE Period(Years):            | 10                             |  |
| QP Paid:                      | \$105,459.00                   |  |
| COE Rebate Amount:            | \$102,567.00                   |  |
| Total Rebate Amount:          | \$126,252.00                   |  |

The information contained herein is correct as at 28 Jun 2023

OK