



1

of 2 ?

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref: CS/III23006595/Avp3

64 CECIL STREET

Date: 30/06/2023

#05-02 IOB BUILDING SINGAPORE 049711

Code: III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 6925S	Veh. Inspected	SKD 8950D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	LOGAN	Assign Date	30/06/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	24/06/2023	Inspection Date	
Survey held at	THE WHEELERS AUTO SERVICES PTE LTD 2 KAKI BUKIT AVENUE 2, #-1-14, KAKI BUKIT AUTOHUB, SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--