

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

30/06/2023 10:32

JOB-NO: 50115229

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHB4838T TRANS: AUTO
 MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI
 OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD
 JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: KMHC851CVLU178639
 ENGINE: G4LEKU362990

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREAS	1.00	1,400.00	0.00	1,400.00		Y	600
2 TO RUST PROOFING OF AFFECTED AREAS	1.00	170.00	0.00	170.00		Y	40
3 TO DIAGNOSTIC, CHECK WIRING, LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	180.00	0.00	180.00		Y	180.80
4 TO READJUST AND REALIGN HEADLAMP AIM	1.00	100.00	0.00	100.00		Y	30
5 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	120.00	0.00	120.00		Y	160 X
6 TO VACUUM AND TOPUP A/C GAS	1.00	120.00	0.00	120.00		Y	X
7 TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00		Y	X
8 TO RESPRAY FRONT BUMPER COVER	1.00	250.00	0.00	250.00		Y	200
9 TO RESPRAY FRONT BUMPER CENTER UPPER MOULDING	1.00	250.00	0.00	250.00		Y	100
10 TO RESPRAY FRONT BUMPER LOWER MOULDING	1.00	250.00	0.00	250.00		Y	X
11 TO RESPRAY FRONT BUMPER FOG LAMP COVER	1.00	250.00	0.00	250.00		Y	X
12 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00		Y	200
13 TO RESPRAY FRONT DOOR PANEL	1.00	250.00	0.00	250.00		Y	X
14 TO RESPRAY FRONT SIDE MIRROR	1.00	250.00	0.00	250.00		Y	50
15 TO RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00		Y	200
16 TO RESPRAY A PILLAR RH	1.00	250.00	0.00	250.00		Y	100
TOTAL:		4,600.00	0.00	4,600.00			
MATERIALS							
1 FRONT BUMPER <i>del</i>	1.00	430.90	86.18	344.72	L	Y	
2 FRONT RH BUMPER RETAINER <i>re</i>	1.00	28.00	5.60	22.40	L	Y	
3 FRONT RH BUMPER SIDE SUPPORT BRACKET <i>re</i>	1.00	12.00	2.40	9.60	L	Y	
4 FRONT BUMPER ENERGY ABSORBER X	1.00	86.90	17.38	69.52	L	Y	
5 FRONT BUMPER REINFORCEMENT X	1.00	1,075.10	215.02	860.08	L	Y	
6 FRONT BUMPER CENTER UPPER MOULDING <i>re</i>	1.00	284.90	56.98	227.92	L	Y	
7 FRONT BUMPER LOWER GRILLE X	1.00	186.90	37.38	149.52	L	Y	
8 FRONT BUMPER LOWER LIP X	1.00	35.10	7.02	28.08	L	Y	
9 FRONT RH HEADLAMP ?	1.00	2,110.30	422.06	1,688.24	L	Y	
10 FRONT END MODULE CARRIER X	1.00	949.30	189.86	759.44	L	Y	
11 WIPER TANK ? X	1.00	150.80	30.16	120.64	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
12 FRONT RH WHEEL RIM COVER <i>Sc</i>	1.00	346.40	69.28	277.12	L	Y	
13 FRONT RH FENDER PANEL <i>bt</i>	1.00	588.80	117.76	471.04	L	Y	
14 FRONT RH FENDER LINER <i>X</i>	1.00	114.70	22.94	91.76	L	Y	
15 FRONT RH FENDER EMBLEM <i>an</i>	1.00	26.80	5.32	21.28	L	Y	
16 FRONT RH SIDE MIRROR <i>ba</i>	1.00	1,054.80	210.92	843.68	L	Y	
17 FRONT RH DELTA GARNISH <i>X</i>	1.00	42.80	8.56	34.24	L	Y	
18 FRONT BUMPER CLIP SET <i>an</i>	1.00	55.00	0.00	55.00	S	Y	<u>30</u>
19 FRONT BUMPER RIVET SET <i>an</i>	1.00	50.00	0.00	50.00	S	Y	<u>30</u>
20 FRONT FENDER INNER SHIELD CLIP SET <i>an</i>	1.00	55.00	0.00	55.00	S	Y	<u>30</u>
21 FRONT FENDER ADS STICKER RH	1.00	250.00	0.00	250.00	S	Y	<u>60</u>
22 SIDE SKIRT ADVERTISEMENT STICKER	1.00	250.00	0.00	250.00	S	Y	<u>X</u>
23 FRONT DOOR STICKER-COMFORT DELGRO RH	1.00	120.00	0.00	120.00	S	Y	<u>X</u>
24 FRONT DOOR ADS STICKER RH	1.00	250.00	0.00	250.00	S	Y	<u>X</u>
25 RADIATOR COOLANT	1.00	100.00	0.00	100.00	S	Y	<u>X</u>
TOTAL:		8,654.10	504.82	7,149.28			
TOTAL PARTS & LABOUR :		13,254.10	1,504.82	11,749.28			

EXCESS/LOADING:S\$ 0.00

No. Of Day: 5 days

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM S\$

DATE OF SURVEY: 03 / 07 / 23 @ 1500

SURVEYED BY: Rosul

CONTACT NO: 9006068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STAAUTOCENTRE

TEL:

FAX:

Rosul after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: