

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: WAN.VK.518405.N KCP Date: 27th Jul 2023

Our Ref: CS1/LAW23006668/Dvy3e2

M/s Riaz LLC

133 New Bridge Road #09-09 Chinatown Point Singapore 059413

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FC 9119X INSURED VEHICLE: FBQ 7319Y

ACCIDENT DATE: 07/02/2020

We thank you for your instruction on 04/05/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FC 9119X from M/s Advanced Automotive Consultancy Pte Ltd.
- b) Survey report by Priority Services with colour photographs.
- c) Final Repair Bill of FC 9119X from M/s Equator Brotherhood.
- d) Singapore Accident Statement and Police Report of Vehicles FC 9119X.
- e) Colour damaged vehicle photographs of FC 9119X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FC 9119X

Make & Model : Yamaha GDR155A (AEROX)

Chassis Number : MH3SG4640JJ044441

Year of Registration : 2018 Engine Capacity : 155 cc

- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.