



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23006709/Uny3m4 Date: 21/07/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SNK 3376Y	Veh. Inspected	GBM 1243S
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS23/2076	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	03/07/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	SUZUKI EVERY JOIN (A)	c.c	658
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	DA17V634322	Colour	SILVER
	Odometer	7535 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	145/80R12	YOKOHAMA	6 mm
	L/H Front Tyre	145/80R12	YOKOHAMA	6 mm
	R/H Rear Tyre	145/80R12	YOKOHAMA	6 mm
	L/H Rear Tyre	145/80R12	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	30/06/2023	Inspection Date	04/07/2023
	Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808		
<b>5a. Remarks</b>				
	A)REGISTRATION DATE: 30 NOV 2022 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	