



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

10 EUNOS ROAD 8
SINGAPORE POST CENTRE #09-04A
SINGAPORE 408600

Ref: CS/ICS23006711/Aqy3

Date: 04/07/2023

Code: ICS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKT 5087G
Policy No.	AGC/LEO/0001/2023	Coverage (\$)	0.00
Claim No.	DMPC2300506H/CT	Excess (\$)	0.00
Assign From	CRYSTABELLE TAN	Assign Date	03/07/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	25/06/2023	Inspection Date	05/07/2023
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.