

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23006712/UQY3M4**Date:** 12/07/2023**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001969935

Claimant Vehicle No : GBJ5445R**Insured Vehicle No :** GBD910D

Date of Loss: 30/06/2023

Nature of Claim: TP

Claim No: 320752

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ5445R**

Make & Model: NISSAN NV200, 1.5 MT (M)

Engine No: K9KE628D675630

Reg. Date: 22/05/2019 (Man. Year: 2019)

Chassis No: VSKYBAM20Z0177972

Colour: Silver

Odometer: 113504 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R14

Rear Tyre Size: 185/65R14

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,427.47	971.97	2,455.50	71.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	1,060.00	530.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,017.47	2,031.97	2,985.50	59.50
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	5,017.47	1,600.00	3,417.47	68.11

INSPECTION

Date of Assignment: 04/07/2023

Date Inspected: 05/07/2023

Inspected At:

T K LEE AUTOMOTIVE PTE LTD
NO. 1 KAKI BUKIT AVE 6
#02-47 AUTOBAY
SINGAPORE 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Jul 2023)	
Parts:	N/A	NISSAN NV200 1.5 MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ5445R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP -RH	Scratched	304.00 FN	*280.60 FN
2	1		*REAR BUMPER	Grazed	632.70 FN	*632.70 FN
3	1		*REAR BUMPER SIDE RETAINERS -R/L	Not Necessary	97.80 FN	*- FN
4	1		*REAR FENDER -RH	Repair	1,791.60 FN	*- FN
5	1		*REAR SHOCK ABSORBER -RH	Not Necessary	280.60 FN	*- FN
6	1		*REAR WHEEL BEARING -RH	Not Necessary	451.60 FN	*- FN
7	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
8	1		*SET REAR WHEEL HUB CAB -RH	Cracked	180.00 FS	*120.00 FS
					Sub Total (\$\$)	3,783.30 1,063.30
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	355.83 91.33
					Total Parts (\$\$)	3,427.47 971.97

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENT, CUT/WELD REAR FENDER AND REPLACE ACCIDENT	New	700.00	500.00
2	TO SPRAY PAINT ON ACCIDENT PORTION	New	500.00	480.00
3	TO CHECK WIRING	New	30.00	20.00
4	TO REMOVE AND REPLACE REAR UNDERCARRIAGE	New	200.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
6	TO TUFF KOTE	New	40.00	0.00
Gross Labour Cost (\$\$)			1,590.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >