



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22008610/Dqp3m4-1	
			Date: 05/07/2023	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMQ 854J	Veh. Inspected	SJT 9846T	
Policy No.	DMPCSNW00200862102	Coverage (\$)	0.00	
Claim No.	SNM22D206233/C02	Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	04/07/2023	
2. Vehicle Particulars & Condition				
Make & Model	HONDA AIRWAVE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GJ11307125	Colour	GREY	
Odometer	158997 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/55 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/55 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	195/55 R15	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/08/2022	Inspection Date	02/09/2022	
Survey held at	TECHNEAT PTE LTD 8 KAKI BUKIT AVENUE 4, #03-38/39 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	