



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/CTI22008610/qp3-1

CHINA TAIPING INSURANCE (S) PTE LTD

Ref: ~~CS3/CTI22008610/Sqys~~

3 ANSON ROAD #16-00

Date: ~~02/09/2022~~ 04/07/2023

SPRINGLEAF TOWERSINGAPORE 079909

Code: CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMQ 854J	Veh. Inspected	SJT 9846T
Policy No.	DMPCSNW00200862102	Coverage (\$)	0.00
Claim No.	SNM22D206233/C02	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	02/09/2022 04/07/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	31/08/2022	Inspection Date	02/09/2022
Survey held at	TECHNEAT PTE LTD 8 KAKI BUKIT AVENUE 4, #03-38/39 PREMIER @ KAKI BUKIT		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--