

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D, #02-15**  
**417883**

**Insurer Reference:**  
**Repairer Reference: 23/CN/OD-390(07)**  
**Date calculated: 04/07/2023 2:29 PM**

**Full Report**  
**Registration: SMX3308M**  
**Printed: 04/07/2023 6:01 PM**

**Summary Information**

**Claim**

|                        |                |                   |                                             |
|------------------------|----------------|-------------------|---------------------------------------------|
| Location:              | Singapore (SG) | Work Provider:    | China Taiping Insurance (Singapore) Pte Ltd |
| Printed by:            | Gary Seah      | Currency:         | SGD                                         |
| Claim Reference:       |                | Date of Incident: | 01/07/23                                    |
| Estimated Repair Time: |                | Hire Car Start:   |                                             |
| Actual Repair Days:    |                | Hire Car End:     |                                             |

3500  
~~Excess 83500~~

**Vehicle Details**

**Vehicle**

Manufacturer: MERCEDES-BENZ  
 Model: B-CLASS (W246)  
 Sub Model: B 200  
 Model Sheet Number: 03 81 42  
 Registration: SMX3308M  
 VIN number: WDD2462432J096722  
 Odometer:

**Model Specs**

|                      |                      |                      |                      |
|----------------------|----------------------|----------------------|----------------------|
| FROM J080577/N012206 | MODEL 2013           | A/C THERMATIC        | LED DAYT RUN LAMPS   |
| RAIN SENSOR          | DIPPING DOOR MIRROR  | COLLISION WARNER     | ELECT FOLDING MIRROR |
| AUDIO SYSTEM 20 CD   | BI-XENON HEADLAMPS   | LIGHT-/VIEW PACKAGE  | HEADLAMP WASHER UNIT |
| LEATHER PAD ARTICO   | ELECT LUMBAR ADJUST  | CHROME PACKAGE       | MULTI FUNCT S-WHEEL  |
| S/WHEEL TIP SWITCHES | DRIVER SEAT MEMORY   | PASS SEAT MEMORY     | TRIM MATRIX OPTICS   |
| SEAT COMFORT PACKAGE | MEDIA INTERFACE      | ILLUM SUN VISOR      | DRIVER SEAT TRAY     |
| PASS SEAT ST/BOX     | FRT SEAT LUGGAGE NET | SOCKET 12V           | STORAGE PACKAGE      |
| ECO START/STOP       | CRUISE CONTROL       | 7 SPEED AUTOMATIC    | TYRES 205/55 R16..H  |
| WHEELS 6.5J X 16 ALU | TYRE W/FLAT RUNNING  | LOAD COMPART PACKAGE | KNEE AIRBAG          |
| ELECTRIC SUNROOF     | PARKTRONIC           | LUGGAGE COMP COVER   | TWO COAT METALLIC    |
| PREPARE OFF VEHICLE  | CLEAR COAT HARD      |                      |                      |

not Adham  
 this means  
 5/7/23  
 2/55  
 16 days

**Labour**

| Code       | Description                                                                                           | Time Base 10 WU/h | Price = 42.00 SGD/h |           |
|------------|-------------------------------------------------------------------------------------------------------|-------------------|---------------------|-----------|
|            |                                                                                                       |                   | WU                  | Price SGD |
| 54-1011 01 | SHORT TEST<br>INCLUDES: CONNECT + DISCONNECT STAR<br>DIAGNOSIS,<br>PRINT DATA,<br>DELETE ERROR MEMORY |                   | 3.0                 | 12.60     |
| 54-7989 01 | R + R BATTERY EARTH CABLE<br>(WHEN DISCONNECTING ELECTRIC PLUG AND<br>SOCKET CONNECTIONS)             |                   | 2.0                 | 8.40      |
| 61-1069 01 | R + R COMPL LWR ENGINE COMPARTMENT COVER                                                              |                   | 5.0                 | 21.00     |
| 61-1116 01 | R + R L/UNDERFLOOR COVER                                                                              |                   | 4.0                 | 16.80     |
| 61-1117 02 | R + R R/UNDERFLOOR COVER                                                                              |                   | 4.0                 | 16.80     |
| 88-1102 01 | R + R FRONT BUMPER CPL                                                                                |                   | 7.0                 | 29.40     |

Audatex System Using Manufacturer Times

PRINT DATE 04/07/2023

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

| Code        | Description                                                                                                                                                                                                                                                                                              | WU   | Price SGD |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 88-1302 01  | ADD TO R + R FRONT BUMPER<br>(VEHICLE WITH DAYTIME RUNNING LIGHT)                                                                                                                                                                                                                                        | 1.0  | 4.20      |
| 88-1153 01  | ADDITION TO R + R FRONT BUMPER<br>(VEHICLE WITH COLLISION WARN SYS)                                                                                                                                                                                                                                      | 1.0  | 4.20      |
| 88-1130 01  | DIS + ASS FRONT BUMPER<br>(BUMPER REMOVED)<br>AFTER CHECK: RENEW PARTS IF NECESSARY                                                                                                                                                                                                                      | 7.0  | 29.40     |
| 88-1357 01  | ADD TO DIS/ASS FRONT BUMPER CPL<br>(LUXURY VERSION VEHICLE)                                                                                                                                                                                                                                              | 1.0  | 4.20      |
| 88-1360 ZAX | ADDITION TO DIS + ASS FRONT BUMPER<br>(VEHICLE WITH PARK ASSISTANT)                                                                                                                                                                                                                                      | 2.0  | 8.40      |
| 82-4810 01) | RENEW BOTH HEADLAMPS<br>(BUMPER REMOVED)                                                                                                                                                                                                                                                                 | 3.0  | 12.60     |
| 82-4889 01  | ADDITIONAL TO RENEW BOTH HEADLAMPS<br>(VEHICLE WITH XENON HEADLAMP)                                                                                                                                                                                                                                      | 3.0  | 12.60     |
| 88-3983 01  | RENEW R/FR WING<br>(BUMPER REMOVED/DETACHED)<br>INCLUDES: R/F WHEELHOUSE COVER CPL<br>REMOVE AND REFIT                                                                                                                                                                                                   | 8.0  | 33.60     |
| 60-1331 01  | R + R ATTACHED PARTS OF THE ENGINE<br>COMPARTMENT FOR RENEWAL OF THE FRONT<br>MODULE<br>INCLUDES: R + R ALL ATTACHED PARTS IN<br>THE REPAIR SECTION                                                                                                                                                      | 11.0 | 46.20     |
| 62-1266 01  | FRONT CROSS MEMBER AND BRACE BETWEEN<br>THE WHEELHOUSES COMPLETE R + R                                                                                                                                                                                                                                   | 14.0 | 58.80     |
| 62-1270 01  | R + R RADIATOR CARRIER OR<br>REPLACE (STRIPPED)<br>INCLUDES: L + R CRASHBOX R + R                                                                                                                                                                                                                        | 3.0  | 12.60     |
| 72-1515 01  | RENEW R/F DOOR AND CONVERT PARTS<br>INCLUDES: DOOR TRIM REMOVE AND REFIT<br>AND ALL ATTACHED PARTS ASSEMBLE                                                                                                                                                                                              | 30.0 | 126.00    |
| 88-3231 01) | RENEW R/DOOR MIRROR (REMOVED)                                                                                                                                                                                                                                                                            | 2.0  | 8.40      |
| 72-1640 01  | RENEW R/R DOOR AND CONVERT PARTS<br>INCLUDES: DOOR TRIM REMOVE AND REFIT<br>AND ALL ATTACHED PARTS ASSEMBLE                                                                                                                                                                                              | 30.0 | 126.00    |
| 60-4370 01) | R + R ATTACHED PARTS AND TRIMS OF THE<br>R/OUTER SIDEMEMBER SHELL                                                                                                                                                                                                                                        | 11.0 | 46.20     |
| 63-1124 01  | RENEW R/OUTER SILL SIDEMEMBER SHELL<br>PANELLING CPL                                                                                                                                                                                                                                                     | 71.0 | 298.20    |
| 60-2168 ZAX | R + R ATTACHED PARTS AT REAR COVER PANEL<br>TO REPLACE R/SIDE PANEL<br>INCLUDES: REAR PANEL TRIMS,<br>BOOT COMPART, INTERIOR IN REAR, ON ENTR-<br>ANCE, REAR BUMPER, TAILLAMP,<br>PARTITION PANEL UNDER WING, HEAD-<br>LINING, SIDE WINDOW AIRBAG AND SEAT BELT<br>REMOVE AND REFIT, SIDE WINDOW REPLACE | 52.0 | 218.40    |
| 63-1890 01  | RENEW R/R SIDE PANEL                                                                                                                                                                                                                                                                                     | 77.0 | 323.40    |
| 72-1901 01  | R + R TAILGATE                                                                                                                                                                                                                                                                                           | 17.0 | 71.40     |
| 68-1257 01  | ADD TO LOAD COMPARTMENT SIDE TRIM R + R<br>(VEHICLE WITHOUT VARIO-SYSTEM)                                                                                                                                                                                                                                | 3.0  | 12.60     |
| 68-1258 01  | ADD TO LOAD COMPARTMENT SIDE TRIM R + R<br>(VEHICLE WITH HEIGHT ADJUST BOOZFLOOR)                                                                                                                                                                                                                        | 1.0  | 4.20      |
| 60-1234 01) | R + R RADIATOR                                                                                                                                                                                                                                                                                           | 3.0  | 12.60     |

| Code                             | Description                                                                                              | WU           | Price SGD       |
|----------------------------------|----------------------------------------------------------------------------------------------------------|--------------|-----------------|
| 20-4000 02)                      | RENEW RADIATOR (REMOVED)                                                                                 | 1.0          | 4.20            |
| 20-6461 01                       | R + R FAN UNIT                                                                                           | 5.0          | 21.00           |
| 83-6541 ZAX                      | R + R CONDENSER                                                                                          | 4.0          | 16.80           |
| 33-1855 ZAX                      | R + R FRONT AXLE CARRIER                                                                                 | 32.0         | 134.40          |
| 33-1859 ZAX                      | RENEW FRONT AXLE SUPPORT (REMOVED)                                                                       | 5.0          | 21.00           |
| 33-3510 01)                      | R + R L/F STEERING KNUCKLE                                                                               | 12.0         | 50.40           |
| 33-3570 01)                      | R + R R/F STEERING KNUCKLE                                                                               | 12.0         | 50.40           |
| 32-1955 01)                      | R + R L/F STRUT                                                                                          | 7.0          | 29.40           |
| 32-1960 01)                      | R + R R/F STRUT                                                                                          | 5.0          | 21.00           |
| 32-1908 01)                      | DISS/ASS L/F SUSPENSION STRUT REMOVED                                                                    | 3.0          | 12.60           |
| 32-1914 01)                      | DISS/ASS R/F SUSPENSION STRUT                                                                            | 3.0          | 12.60           |
| 32-1920 01)                      | DIS + ASS FRONT SPRING STRUT/S (REMOVED)                                                                 | 3.0          | 12.60           |
| 40-2410 01                       | R + R LEFT FRONT TYRE                                                                                    | 3.0          | 12.60           |
| 40-2410 01                       | R + R RIGHT FRONT TYRE                                                                                   | 3.0          | 12.60           |
| 40-2410 01                       | R + R RIGHT REAR TYRE                                                                                    | 3.0          | 12.60           |
| 40-2055 01                       | L/FRONT WHEEL BALANCE                                                                                    | 2.0          | 8.40            |
| 40-2055 01                       | R/FRONT WHEEL BALANCE                                                                                    | 2.0          | 8.40            |
| 40-2055 01                       | BALANCE R/R WHEEL                                                                                        | 2.0          | 8.40            |
| 32-4580 01                       | R + R RIGHT REAR COIL SPRING                                                                             | 7.0          | 29.40           |
| 32-4590 01                       | ADD TO R + R REAR COIL SPRING<br>(VEHICLE WITHOUT SPORTS SUSPENSION)                                     | 3.0          | 12.60           |
| 35-7831 01)                      | REMOVE AND REFIT R/R UPP CONTROL ARM                                                                     | 5.0          | 21.00           |
| 32-3331 01)                      | R + R RIGHT REAR STABILIZER LINKAGE                                                                      | 3.0          | 12.60           |
| 32-1071 01)                      | R + R RIGHT REAR SHOCK ABSORBER                                                                          | 4.0          | 16.80           |
| 35-5790 01)                      | R + R R/R WHEEL CARRIER                                                                                  | 7.0          | 29.40           |
| 35-8011 01)                      | R + R R/REAR TRAILING LINK                                                                               | 5.0          | 21.00           |
| 35-7857 01)                      | R + R RIGHT REAR TIE ROD                                                                                 | 4.0          | 16.80           |
| 49-7000 01                       | R + R EXHAUST SYSTEM CPL                                                                                 | 8.0          | 33.60           |
| 83-1762 01                       | AIR-CONDITIONING SYSTEM DRAIN FLUID,<br>EXHAUST, REFILL, PRESSURE TEST<br>(FOR ALL WORK ON THE SYSTEM)   | 5.0          | 21.00           |
| 40-6500 01                       | ALIGN VEHICLE<br>INCLUDES: ALIGN FRONT AND REAR TOE AND<br>CAMBER,<br>CHECK FRONT AND REAR VEHICLE LEVEL | 7.0          | 29.40           |
| 40-4064 01                       | ADJUST FRONT WHEEL TOE<br>(DURING ALIGNMENT)                                                             | 2.0          | 8.40            |
| 0471                             | BONNET REPAIR                                                                                            | 15.0*        | 63.00 ✓         |
| 1112                             | R/F WHEELHOUSE ASSY REPAIR                                                                               | 20.0*        | 84.00 ✓         |
| 2084                             | R/F DOOR FRAME REPAIR                                                                                    | 30.0*        | 126.00 ✗        |
| 2142                             | R/INNER SILL REPAIR                                                                                      | 30.0*        | 126.00 ✓        |
| 2583                             | REAR BUMPER COVER REPAIR                                                                                 | 10.0*        | 42.00 ✗         |
| 4258                             | R/FLOOR REPAIR                                                                                           | 40.0*        | 168.00 ✓        |
| <b>Labour Cost</b>               |                                                                                                          | <b>Hrs</b>   | <b>WU</b>       |
| <b>Panel / Mechanical Labour</b> |                                                                                                          | <b>67.90</b> | <b>679.0</b>    |
| <b>Alignment</b>                 |                                                                                                          |              |                 |
| <b>Measuring Work</b>            |                                                                                                          | <b>0.90</b>  | <b>9.0</b>      |
| <b>Total of Labour</b>           |                                                                                                          |              | <b>2,889.60</b> |

**Paint**

| Paint Work |                                         | SYSTEM AZT | Time Basis 10 WU/h |           |
|------------|-----------------------------------------|------------|--------------------|-----------|
| Code       | Description - TWO COAT METALLIC         |            | WU                 | Price SGD |
|            | R/F WING NEW PART PAINTING              |            | 10.0               |           |
|            | RIGHT FRONT DOOR NEW PART PAINTING      |            | 17.0               |           |
|            | R/R DOOR NEW PART PAINTING              |            | 16.0               |           |
|            | RIGHT SILL PANEL CPL NEW PART PAINTING  |            | 16.0               |           |
|            | R/RR SIDE PANEL NEW PART PAINTING       |            | 19.0               |           |
|            | FRONT BUMPER COVER NEW PART PAINT K1R   |            | 13.0               |           |
|            | R/F OUTER SENSOR NEW PART PAINT K1R     |            | 3.0                |           |
|            | R/F CTR PARKING SENS NEW PART PAINT K1R |            | 3.0                |           |
|            | R/SILL PANELLING NEW PART PAINT K1R     |            | 7.0                |           |
|            | BONNET REPAIR PAINTING <50%             |            | 21.0               |           |
|            | R/F DOOR FRAME REPAIR PAINTING <50%     |            | 11.0               |           |
|            | R/OUTER A-PILLAR REPAIR PAINTING <50%   |            | 10.0               |           |
|            | REAR BUMPER COVER REPAIR PAINT PLASTIC  |            | 15.0               |           |
|            | R/F WHEELHOUSE ASSY SURFACE PAINT       |            | 6.0                |           |
|            | R/FLOOR SURFACE PAINT                   |            | 10.0               |           |

**Paint Material Per Part**

| Code | Description                             | Price SGD |
|------|-----------------------------------------|-----------|
| 0742 | R/F WING NEW PART PAINTING              | 20.12     |
| 1482 | RIGHT FRONT DOOR NEW PART PAINTING      | 47.99     |
| 1782 | R/R DOOR NEW PART PAINTING              | 43.34     |
| 2102 | RIGHT SILL PANEL CPL NEW PART PAINTING  | 17.05     |
| 3482 | R/RR SIDE PANEL NEW PART PAINTING       | 21.45     |
| 0283 | FRONT BUMPER COVER NEW PART PAINT K1R   | 64.45     |
| 0362 | R/F OUTER SENSOR NEW PART PAINT K1R     | 0.49      |
| 0364 | R/F CTR PARKING SENS NEW PART PAINT K1R | 0.49      |
| 2208 | R/SILL PANELLING NEW PART PAINT K1R     | 27.06     |
| 0471 | BONNET REPAIR PAINTING <50%             | 41.34     |
| 2084 | R/F DOOR FRAME REPAIR PAINTING <50%     | 11.95     |
| 2242 | R/OUTER A-PILLAR REPAIR PAINTING <50%   | 9.04      |
| 2583 | REAR BUMPER COVER REPAIR PAINT PLASTIC  | 42.12     |
| 1112 | R/F WHEELHOUSE ASSY SURFACE PAINT       | 12.95     |
| 4258 | R/FLOOR SURFACE PAINT                   | 29.88     |

**Labour Cost - Paint**

|                                | Hrs          | WU           | Price SGD     |
|--------------------------------|--------------|--------------|---------------|
| Factor                         |              |              | 42.00 SGD/h   |
| Time Paint                     |              | 177.0        |               |
| Preparation Main Work Metal    | 2.50         | 25.0         | 105.00        |
| Preparation Comp. Work Plastic | 0.80         | 8.0          | 33.60         |
| <b>Total</b>                   | <b>21.00</b> | <b>210.0</b> | <b>882.00</b> |

# Material Cost - Paint

|                                     |           |
|-------------------------------------|-----------|
| New Part Painting                   | Price SGD |
| New Part Painting - Plastic K1R     | 149.95    |
| Repair Painting                     | 92.49     |
| Repair Painting Plastic             | 62.33     |
| Surface-/Blend Paint                | 42.12     |
| Material-constant Metal Preparation | 42.83     |
| Material-constant Plastic           | 28.60     |
| Total                               | 12.70     |
|                                     | 431.02    |

## Spare Parts

|      |                          |                   |             | prices as at 2015-06-01 | Price SGD |
|------|--------------------------|-------------------|-------------|-------------------------|-----------|
| Code | Description              | Part Number       | Part Source |                         |           |
| 0283 | FRONT BUMPER COVER       | 246 880 0540 9999 | Original    | Dos 1,100.00            | ✓         |
| 0304 | R/F BUMPER COVER         | 246 885 0722      | Original    | mis 65.00               | ✓         |
| 0305 | FRONT BUMPER GRILLE      | 246 885 1122      | Original    | car 95.00               | ✓         |
| 0310 | R/F TRIM                 | 246 885 0574      | Original    | trim 105.00             | ✓         |
| 0311 | L/F BUMPER MOULDING      | 246 885 0421      | Original    | scr 85.00               | ✓         |
| 0312 | R/F BUMPER MOULDING      | 246 885 0521      | Original    | scr 85.00               | ✓         |
| 0336 | FRONT IMPACT DAMPER      | 246 885 0037      | Original    | trim 120.00             | ✓         |
| 0340 | FRT BUMPER C-MEMBER      | 246 885 0365      | Original    | scr 95.00               | ✓         |
| 0349 | FRT BUMPER CLAMP KIT     | USE SINGLE PARTS  | Original    | scr 40.00               | ✓         |
| 0362 | R/F OUTER SENSOR         | 000 905 0342      | Original    | multifunction 195.00    | ✓         |
| 0364 | R/F CTR PARKING SENS     | 000 905 0242      | Original    | multifunction 195.00    | ✓         |
| 0377 | FRT BUMPER W/<br>HARNESS | 246 540 2205      | Original    | 165.00                  | ?         |
| 0405 | FRONT GRILLE             | 246 880 1483 9982 | Original    | cm 550.00               | ✓         |
| 0432 | STAR EMBLEM              | 207 817 0316      | Original    | cm 50.00                | ✓         |
| 0433 | BASE PLATE               | 164 888 0411      | Original    | 320.00                  | ?         |
| 0561 | LEFT HEADLAMP ASSY       | 246 820 0339      | Original    | 1,950.00                | ?         |
| 0562 | RIGHT HEADLAMP ASSY      | 246 820 0439      | Original    | 3 no 1,950.00           | ✓         |
| 0626 | R/H-LAMP WASHER JET      | 246 860 0647      | Original    | cm 145.00               | ✓         |
| 0628 | R/SPRING                 | 203 869 0034      | Original    | mis 50.00               | ✓         |
| 0640 | R/F DAYTIME RUN LAMP     | 204 906 9200      | Original    | cm 350.00               | ✓         |
| 0742 | R/F WING                 | 246 881 0201      | Original    | Dos 495.00              | ✓         |
| 0789 | L/F WING CLAMP KIT       | USE SINGLE PARTS  | Original    | scr 40.00               | ✓         |
| 0790 | R/F WING CLAMP KIT       | USE SINGLE PARTS  | Original    | scr 40.00               | ✓         |
| 0841 | L/F WHEELHOUSE<br>COVER  | 246 690 0100      | Original    | trim 160.00             | ✓         |
| 0842 | R/F WHEELHOUSE<br>COVER  | 246 690 0200      | Original    | trim 160.00             | ✓         |
| 0930 | CTR FRT REINF            | 246 620 0234 64   | Original    | 720.00                  | ?         |
| 1001 | FRONT CROSSMEMBER        | 246 620 1100      | Original    | Bent 260.00             | ✓         |
| 1004 | R/R ABSORBER<br>BRACKET  | 246 626 0088      | Original    | 80.00                   | ?         |
| 1005 | RADIATOR<br>CROSSMEMBER  | 246 620 0019      | Original    | 320.00                  | ?         |
| 1482 | RIGHT FRONT DOOR         | 246 720 0205 64   | Original    | scr/Bent 1,250.00       | ✓         |
| 1492 | R/F DOOR INN RUBBER      | 009 989 9485      |             | 0.00                    | ✓         |
| 1510 | R/F DOOR SEAL            | 099 727 0300      | Original    | scr 230.00              | ✓         |
| 1746 | R/MIRROR BASE            | 246 810 0676      | Original    | scr 550.00              | ✓         |
| 1782 | R/R DOOR                 | 246 730 0205      | Original    | scr/Bent 1,400.00       | ✓         |
| 1790 | R/R DOOR INN RUBBER      | 010 989 1685      |             | 0.00                    | ?         |
| 1810 | R/R DOOR SEAL            | 099 727 0300      | Original    | scr 220.00              | ✓         |
| 2102 | RIGHT SILL PANEL CPL     | 246 637 1235      | Original    | Bent 1,400.00           | ✓         |
| 2108 | 2K ADHESIVE R/SIDE       | 012 989 1771 11   |             | 0.00                    | ✓         |

| Code             | Description          | Part Number       | Part Source | Price SGD |   |
|------------------|----------------------|-------------------|-------------|-----------|---|
| 2208             | R/SILL PANELLING     | 246 698 0654 9999 | Original    | 350.00    | ✓ |
| 2210             | R/LWR TRIM MNTG SET  | USE SINGLE PARTS  | Original    | 96.00     | ? |
| 3482             | R/RR SIDE PANEL      | 246 630 1400      | Original    | 1,950.00  | X |
| 3806             | R/R SIDE WINDOW      | 246 670 3301      |             | 0.00      | X |
| 3864             | R/S WINDOW BOND KIT  | 000 989 4905 11   |             | 0.00      | X |
| 4283             | L/F LWR FLOOR COVER  | 246 684 0100      | Original    | 195.00    | ✓ |
| 4284             | R/F LWR FLOOR COVER  | 246 684 0200      | Original    | 195.00    | ✓ |
| 4465             | AIR CON CONDENSER    | 246 500 0454      | Original    | 730.00    | ? |
| 7011             | FRONT AXLE SUPPORT   | 246 620 1200      | Original    | 1,150.00  | ? |
| 7036             | R/F DRIVE SHAFT      | 246 330 2601      | Original    | 1,600.00  | ✓ |
| 7047             | L/F LWR CONTROL ARM  | 246 330 4700      | Original    | 365.00    | ✓ |
| 7048             | R/F LWR CONTROL ARM  | 246 330 4800      | Original    | 365.00    | ✓ |
| 7085             | L/F STEERING KNUCKLE | 246 332 0100      | Original    | 650.00    | ? |
| 7086             | R/F STEERING KNUCKLE | 246 332 0200      | Original    | 650.00    | ? |
| 7087             | L/FR SHOCK ABSORBER  | 246 323 2900      | Original    | 480.00    | ? |
| 7088             | R/FR SHOCK ABSORBER  | 246 323 3000      | Original    | 480.00    | ? |
| 7201             | L/FR WHEEL           | 246 401 0500 9765 | Original    | 800.00    | ✓ |
| 7202             | R/FR WHEEL           | 246 401 0500 9765 | Original    | 800.00    | ✓ |
| 7261             | FRONT STABILISER     | 246 320 3411      | Original    | 230.00    | ? |
| 7263             | L/F STABI LINKAGE    | 246 320 0689      | Original    | 65.00     | ✓ |
| 7264             | R/F STABI LINKAGE    | 246 320 0689      | Original    | 65.00     | ✓ |
| 7300             | STEERING GEAR        | 246 460 4601      | Original    | 3,000.00  | ✓ |
| 7761             | RADIATOR             | 246 500 1303      | Original    | 560.00    | ? |
| 7789             | HEATER BLOWER        | 246 500 0093      | Original    | 350.00    | ? |
| 8730             | INTERCOOLER          | 246 500 0100      | Original    | 620.00    | ✓ |
| 8779             | FRONT LOWER COVERING | 246 885 0036      | Original    | 220.00    | ✓ |
| 8780             | FRONT CENTRE TRIM    | 246 520 0223      | Original    | 150.00    | ? |
| 9116             | R/R WHEEL SUPPORT    | 246 350 3641      | Original    | 980.00    | ? |
| 9182             | R/R WHEEL HUB        | 246 334 0006      | Original    | 295.00    | ? |
| 9202             | R/RR SHOCK ABSORBER  | 246 320 1831      | Original    | 220.00    | ? |
| 9322             | R/R CONTROL ARM      | 246 350 0506      | Original    | 140.00    | ? |
| 9376             | R/R TIE ROD          | 246 350 0053      | Original    | 125.00    | ? |
| 9386             | R/R UPP CONTROL ARM  | 177 352 1700      | Original    | 160.00    | ? |
| 9552             | R/RR WHEEL           | 246 401 0500 9765 | Original    | 800.00    | ✓ |
| 1000             | GRILLE CLAMP KIT     | CLIPS             | Original    | 16.00     | ✓ |
| 1001             | INTERCOOLER GARNISH  | OUTER             | Original    | 95.00     | ✓ |
| 1002             | AIR BUFFER TOP       | TOP               | Original    | 150.00    | ✓ |
| f: OEM Parts     |                      |                   |             | 0.00      |   |
| n: Non-OEM Parts |                      |                   |             | 34,132.00 |   |
| u: Used parts    |                      |                   |             |           |   |
| <b>Savings</b>   |                      |                   |             | 0.00      |   |
| <b>Subtotal</b>  |                      |                   |             | 34,132.00 |   |
| <b>Total</b>     |                      |                   |             | 34,132.00 |   |

## Extras

| Code                | Description         | Price SGD     |
|---------------------|---------------------|---------------|
| 1003                | NUMBER PLATE        | 35.00* ✓      |
| 1004                | AIRCON COOLANT      | 50.00* ✓      |
| 1005                | RADIATOR COOLANT    | 25.00* ✓      |
| 1006                | R/F TYRE            | 280.00* R22 ✓ |
| 1007                | L/F TYRE            | 280.00* R22 ✓ |
| 1008                | REAR WINDSCREEN GUM | 60.00* X      |
| <b>Total Extras</b> |                     | 730.00        |

## Final Calculation

|                                       | SGD       | SGD              |
|---------------------------------------|-----------|------------------|
| <b>Parts</b>                          | 34,132.00 |                  |
| <b>Total Parts</b>                    |           | <b>34,132.00</b> |
| <b>Labour Time Base 10 WU/h</b>       |           |                  |
| Total 679.0 WU X 42.00 SGD/h          | 2,851.80  |                  |
| Alignment                             |           |                  |
| Measuring Work                        | 37.80     |                  |
| <b>Total of Labour</b>                |           | <b>2,889.60</b>  |
| <b>Total Of Extras</b>                |           | <b>730.00</b>    |
| <b>Paint Work Time Base 10 WU/h</b>   |           |                  |
| Labour Cost 210.0 WU X 42.00 SGD/h    | 882.00    |                  |
| Material Cost                         | 431.02    |                  |
| <b>Total Paint Including Material</b> |           | <b>1,313.02</b>  |
| <b>Repair Cost Excludes GST</b>       |           | <b>39,064.62</b> |
| GST (+8.0%)                           |           | <b>3,125.17</b>  |
| <b>Repair Cost Included GST</b>       |           | <b>42,189.79</b> |

### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.