

Winnie Foo (LKKAUTO)

From: Sherwin Beh (LKK Auto)
Sent: Wednesday, 5 July 2023 1:57 pm
To: Winnie Foo (LKKAUTO)
Subject: Fw: Request for LKK mechanical inspections
Attachments: 6000137661.pdf

Hello Winnie

Kindly open reference number for me on the following 5 cases

TP /IP/11422/2023- **SLM 1260Z**
TP /IP/01489/2023- **GBD 7002D**
TP /IP/16062/2023- **YP 2751Y**
TP /IP/16864/2023- **SLU 2852S**
TP /IP/17077/2023- **PC 6510A**

Best Regards,
Sherwin Beh | Technical Investigator
LKK Auto Consultants
Office: 6256 3561 | Email: SherwinBeh@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Friday, 23 June 2023 1:27 am
To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAUTO) <Naz@lkkauto.com>
Cc: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Siti Haira BATRA (SPF) <Siti_Haira_BATRA@spf.gov.sg>; Syed Muhammad FARID ALBAR (SPF) <Syed_Muhammad_FARID_ALBAR@spf.gov.sg>
Subject: Request for LKK mechanical inspections

Dear Sirs,

cc: Mr Bryan, OC FAIT & SIO Syed, for your information, please

May I seek your assistance to perform a detailed mechanical inspection of the following **6 urgent cases** in the table below.

- 2 The PO attached has been approved by my management.
- 3 Thank you.

SN	IP No.	Brief Facts	Vehicle/s to be inspected
1	TP /IP/11422/2023	On 13 January 2023 sometime before 10.53 p.m., the Involved Party's bus (A1) was travelling on the extreme left of 4-lane road along Yishun Ave 2 towards Yishun Ave 5. He was the 3rd bus from the traffic light stop line. After the traffic light turned green, he proceeded straight. While at the middle of the junction of Yishun Ave 3, B1 (motorcar) came from his right (from Yishun Central) and collided into the central body on the right side of the A1's bus. Upon	SLM1260Z (LV) - Driver (Deceased)

		the impact, D1 (deceased) was trapped in his vehicle and was subsequently extricated from the driver's seat by SCDF. AB arrived at scene and D1 was conveyed unconscious to NTFGH where he succumbed to his injuries and pronounced dead at 11.35 p.m. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	
2	TP /IP/01489/2023	On 16 January 2023 sometime before 8.20 a.m., Deceased was crossing the road at the car park service road when the Involved Party's lorry, collided onto him, causing him to fall onto the road. Deceased was admitted at the hospital till 28 January 2023 where he succumbed to his injuries and passed away at the hospital. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	GBD7002D (LV) - Dr (Involved Party)
3	TP /IP/16062/2023	On 11 June 2023 sometime before 4.13 p.m., Deceased was crossing the road along Old Lim Chu Kang Road when the Involved Party's lorry, collided onto him, causing him to fall onto the road. Deceased was admitted at the hospital till 14 June 2023 where he succumbed to his injuries and passed away at the hospital. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	YP2751Y (LV) - Driv (Involved Party)
4 - 5	TP /IP/16864/2023	On 18 June 2023, sometime before 6.03 p.m., the motorcar (B1) was travelling along PIE (Airport) slip road into Tampines Avenue 5 on the left of 2 lanes road. While approaching the pedestrian crossing, the cyclist (A1) was already seen crossing the road from B1's right to left side. B1 did not stopped at the pedestrian crossing to give way to A1. B1's front left portion collided onto A1's rear left portion of the bicycle. Due to the accident, the pedal cyclist sustained multiple injuries and was reported to be unconscious hence he was conveyed to the Changi General Hospital by an ambulance and still admitted there. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	SLU2852S (LV) - Rid (Involved Party) Black Bicycle (LV) - P Cyclist (Injured Par
6	TP /IP/17077/2023	On 20 June 2023 (Tuesday) at about 8.08 a.m., the driver of minibus, PC6510A (B1) making a right turn out from Blk 239 Yishun Ring Road into Yishun Ring Road when the frontal right portion of his minibus collided onto the Deceased who was standing on the middle of the road. Due to the accident, the Deceased sustained multiple injuries and was conveyed in an unconscious state to KTPH where she subsequently succumbed to his injuries and passed away at the hospital at 3.54 p.m. and was pronounced dead by Dr June. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	PC6510A (LV) - Driv (Involved Party)

Best regards,




Kamaliah Kamis (Miss)


Senior Investigation Officer


Fatal Accident Investigation Team, Traffic Police


DID: (65) 6547 6435 | FAX: (65) 6547 6352


WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act 1935. Please notify the sender immediately if you receive this in error.




ADD
ScamShield app and security features


CHECK
for scam signs and with official sources


TELL
authorities, family and friends


Download the ScamShield app




5 JUL | PSW: SPARK

11 JUL | PST CONVENTION

20 - 21 JUL | PSW LEARNING FESTIVAL

24 JUL - 4 AUG | DISCOVERING GOOD@WORK

FOR MORE INFO, VISIT [GO.GOV.SG/PSW2023](https://go.gov.sg/psw2023)**PUBLIC
SERVICE
WEEK 2023**