

Estimate

LKK AUTO CONSULTANTS PTE LTD Singapore, Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No:	Date: Jul 06 2023
	TP Reg. No: SLZ2449Y	Insured Reg. No: 0
	Ticket No: LKK-J000260	Accident Date: Jul 05 2023
	Policy No: 0	Claim No: 0
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K	Customer: Chong Sengie Vehicle: VOLKSWAGEN GOLF AT 2017 Kilometer: 0 Color: WHITE Fuel: PETROL PH: +65 91177568 Email:	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	FRONT BONNET	Part	1.00	900.00	652.50	247.50	742.50	742.50
2	FRONT BONNET HINGE LH	Part	1.00	70.00	50.75	19.25	57.75	57.75
3	FRONT BONNET HINGE RH	Part	1.00	70.00	50.75	19.25	57.75	57.75
4	FRONT BONNET LOCK	Part	1.00	145.00	105.12	39.88	119.63	119.63
5	FRONT GRILLE ASSY	Part	1.00	280.00	203.00	77.00	231.00	231.00
6	FRONT GRILLE EMBLEM	Part	1.00	75.00	54.37	20.63	61.88	61.88
7	FRONT AIR DUCT	Part	1.00	45.00	32.62	12.38	37.13	37.13
8	FRONT AIR DUCT TOP COVER	Part	1.00	30.00	21.75	8.25	24.75	24.75
9	FRONT HEADLAMP LH	Part	1.00	410.00	297.25	112.75	338.25	338.25
10	FRONT HEADLAMP RH	Part	1.00	410.00	297.25	112.75	338.25	338.25
11	FRONT HEADLAMP UPPER PANEL LH	Part	1.00	45.00	32.62	12.38	37.13	37.13
12	FRONT HEADLAMP UPPER PANEL RH	Part	1.00	45.00	32.62	12.38	37.13	37.13
13	FRONT BUMPER	Part	1.00	680.00	493.00	187.00	561.00	561.00
14	FRONT BUMPER SIDE BRACKET LH	Part	1.00	40.00	29.00	11.00	33.00	33.00
15	FRONT BUMPER LOWER GRILLE	Part	1.00	145.00	105.12	39.88	119.63	119.63
16	FRONT BUMPER SIDE GRILLE LH	Part	1.00	50.00	36.25	13.75	41.25	41.25
17	FRONT BUMPER REINFORCEMENT	Part	1.00	410.00	297.25	112.75	338.25	338.25
18	FRONT BUMPER ABSORBER FOAM	Part	1.00	65.00	47.12	17.88	53.63	53.63
19	FRONT SUPPORT PANEL	Part	1.00	580.00	420.50	159.50	478.50	478.50
20	FRONT SUPPORT BRACE PANEL	Part	1.00	45.00	32.62	12.38	37.13	37.13
21	FRONT A-PILLAR MOULDING LH	Part	1.00	40.00	29.00	11.00	33.00	33.00
22	FRONT BUMPER CLIPS	Part	1.00	50.00	37.50	12.50	37.50	37.50
23	FRONT NUMBER PLATE & HOLDER	Part	1.00	45.00	33.75	11.25	33.75	33.75
24	FRONT AIR DEFLECTOR RH	Part	1.00	30.00	21.75	8.25	24.75	24.75
25	FRONT AIR DEFLECTOR LH	Part	1.00	30.00	21.75	8.25	24.75	24.75
26	FRONT BUMPER CENTER BRACKET	Part	1.00	70.00	50.75	19.25	57.75	57.75
							Taxable Value	3,957.04
							Discount Total	1,319.04
							Grand Total	3,957.04

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
27	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	Labour	-	600.00	572.96	27.04	572.96	572.96

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
28	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC	Labour	-	800.00	800.00	0.00	800.00	800.00
29	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	Labour	-	20.00	20.00	0.00	20.00	20.00
							Taxable Value	1,392.96
							Discount Total	27.04
							Grand Total	1,392.96

	Parts Total	3,957.04
	Labour Total	1,392.96
	GST Total	0.00
	Grand Total	5,350.00
	Balance	5,350.00

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature