

D M G N G A

ben

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SNH870Y

Make & Model: Honda Vezel

Chassis number: RU11330321

No.	Description of spare parts	Qty	Amount S\$
1	Rear bumper	1	\$ 512.70
2	Rear bumper clips	1set	\$ 80.00
3	Rear bumper RH reflector	1	\$ 141.50
4	Rear bumper lower cover	1	\$ 250.00
5	Rear bumper RH side retainer	1	\$ 28.90
6	Rear bumper RH side cover	1	\$ 196.00
7	RH taillamp assy	1	\$ 488.90
8	RH taillamp gasket	1	\$ 23.00
9	RH taillamp lock clips	1set	\$ 22.00
10	RH taillamp panel	1	\$ 156.00
11	RH rear fender <i>Dented</i>	1	\$ 844.00
12	RH rear fender arch moulding <i>at</i>	1	\$ 195.00
13	RH rear fender arch moulding clips <i>me</i>	1set	\$ 70.00
14	RH rear fender inner trim board <i>2 PL</i>	1	\$ 311.00
15	RH rear fender inner trim board clips <i>me</i>	1set	\$ 70.00
16	RH rear sport rim <i>at</i>	1	\$ 813.00
17	RH rear wheel bearing <i>me</i>	1	\$ 317.00
18	RH rear shock absorber	1	\$ 387.00
19	Rear axle beam <i>me</i>	1	\$ 1,651.00
20	RH rear door	1	\$ 921.40
21	RH rear door frame black sticker	1	\$ 38.30

\$ 7,516.70  
 Parts less 20% \$ 1,503.34  
 Total: \$ 6,013.36

No.	Special Nett Items	Qty	Amount S\$
1	Brake fluid	1	\$ 85.00
2	RH rear tyre	1	\$ 500.00
3	RH rear fender joint sealant <i>me</i>	1	\$ 80.00

Total: \$ 665.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,200.00

2	Spray painting on affected areas and panels	\$ <del>1,000.00</del>	200
3	Check wiring and lighting system on affected areas	\$ <del>80.00</del>	30
4	Apply rust coating chemical on affected areas and panels	\$ <del>80.00</del>	60
5	Remove and replace RH rear door inner mechanism to new door	\$ 120.00	+
6	Remove and reinstall roof lining, seats and carpet to assist repair	\$ 450.00	+
7	Test drive and adjust wheel alignment system	\$ <del>180.00</del>	80
8	Remove and replace rear undercarriage parts to assist repair	\$ 550.00	+
		Total: \$ 2,460.00	

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)

Working days: \_\_\_\_\_

Spare Parts: \$ 6,013.36  
Special Nett: \$ 665.00  
Labour: \$ 2,460.00  
**Total Amount: \$ 9,138.36**

Adrian L  
1/s 06/07/23.  
03 Days.