

## Estimate

<b>LKK AUTO CONSULTANTS PTE LTD</b> Singapore, Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No:	Date: Jul 10 2023
	TP Reg. No: SMC2704U	Insured Reg. No: 0
	Ticket No: LKK-J000263	Accident Date: Jul 05 2023
<b>Company Name:</b> INDIA INTERNATIONAL INSURANCE <b>Address:</b> 64 Cecil Street,#04-02 IOB Building <b>City:</b> Singapore <b>Region:</b> Central Singapore <b>Postal Code:</b> 049711 <b>Co.Reg.No:</b> 198703792K	Policy No: D22MFL0002743	Claim No: 0
	<b>Customer:</b> Motoring <b>Vehicle:</b> TOYOTA C-HR PLUS 2018 <b>Kilometer:</b> 0 <b>Color:</b> WHITE <b>Fuel:</b> PETROL <b>PH:</b> +65 81232135 <b>Email:</b>	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	BONNET	Part	1.00	1,223.00	672.65	550.35	672.65	672.65
2	BONNET LOCK	Part	1.00	186.00	102.30	83.70	102.30	102.30
3	BONNET HINGE	Part	2.00	72.00	39.60	64.80	79.20	79.20
4	BONNET INSULATOR	Part	1.00	312.00	171.60	140.40	171.60	171.60
5	FRONT BUMPER	Part	1.00	595.00	327.25	267.75	327.25	327.25
6	FRONT BUMPER REINFORCEMENT	Part	1.00	399.00	219.45	179.55	219.45	219.45
7	FRONT BUMPER SPONGE	Part	1.00	241.00	132.55	108.45	132.55	132.55
8	FRONT BUMPER SIDE RETAINER N/S	Part	1.00	68.00	37.40	30.60	37.40	37.40
9	FRONT GRILLE	Part	1.00	487.60	268.18	219.42	268.18	268.18
10	FRONT GRILLE LOGO	Part	1.00	85.00	46.75	38.25	46.75	46.75
11	HEADLAMP	Part	2.00	3,230.00	1,776.50	2,907.00	3,553.00	3,553.00
12	HEADLAMP LOWER BRACKET	Part	1.00	112.00	61.60	50.40	61.60	61.60
13	FRONT SUPPORT PANEL TOP GARNISH	Part	1.00	166.30	91.46	74.84	91.47	91.47
14	FRONT SUPPORT PANEL	Part	1.00	978.00	537.90	440.10	537.90	537.90
15	AIR CLEANER HOUSING	Part	1.00	698.00	383.90	314.10	383.90	383.90
16	FRONT FENDER LH	Part	1.00	645.10	354.80	290.30	354.81	354.81
17	AIRCON CONDENSOR	Part	1.00	1,120.00	616.00	504.00	616.00	616.00
18	RADIATOR	Part	1.00	1,259.00	692.45	566.55	692.45	692.45
19	FRONT BUMPER CLIPS	Part	10.00	2.00	1.10	9.00	11.00	11.00
20	FRONT SUPPORT PANEL TOP GARNISH CLIPS	Part	1.00	20.00	11.00	9.00	11.00	11.00
							<b>Taxable Value</b>	<b>8,370.46</b>
							<b>Discount Total</b>	<b>6,848.56</b>
							<b>Grand Total</b>	<b>8,370.46</b>

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
21	TO PANEL BEAT, REMOVE AND REPLACE PARTS. REMOVE AND REFIX FRONT SUPPORT PANEL	Labour	-	600.00	439.54	160.46	439.54	439.54
22	TO SPRAY PAINT AFFECTED AREA	Labour	-	800.00	800.00	0.00	800.00	800.00
23	WIRING CHECK	Labour	-	20.00	20.00	0.00	20.00	20.00
24	REFOCUS HEADLAMP BEAM	Labour	-	20.00	20.00	0.00	20.00	20.00
25	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	Labour	-	100.00	100.00	0.00	100.00	100.00
26	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	Labour	-	50.00	50.00	0.00	50.00	50.00
							<b>Taxable Value</b>	<b>1,429.54</b>
							<b>Discount Total</b>	<b>160.46</b>

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
							<b>Grand Total</b>	<b>1,429.54</b>

					<b>Parts Total</b>		<b>8,370.46</b>
					<b>Labour Total</b>		<b>1,429.54</b>
					<b>GST Total</b>		<b>0.00</b>
					<b>Grand Total</b>		<b>9,800.00</b>
					<b>Balance</b>		<b>9,800.00</b>

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

\_\_\_\_\_  
Customer / Authorized Signatory

\_\_\_\_\_  
Service Advisor Signature

\_\_\_\_\_  
Cashier / Authorized Signature