

MY CAR CONSULTANT PTE LTD  
60 JALAN LAM HUAT, CARROS CENTRE  
#05-68 Singapore 737869

NOT Authorized  
11 Sep @ 9800h  
Returning After Pain  
EX TBA

TO	: INDIA INTERNATIONAL	DATE	6-Jul-23
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	O/D CLAIM
<u>VEHICLE DETAILS</u>			
	:	VEHICLE NO	: SMC2704U
	:	MODEL	: TOYOTA CHR
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

REVISED ESTIMATE

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	LIST	TOTAL LIST
1	BONNET 1223	1	\$ 1,312.00	\$ 1,312.00
2	BONNET LOCK 186	1	\$ 351.00	\$ 351.00
3	BONNET HINGE	2	\$ 72.00	\$ 144.00
4	BONNET INSULATOR	1	\$ 312.00	\$ 312.00
5	FRONT BUMPER 595	1	\$ 1,125.00	\$ 1,125.00
6	FRONT BUMPER LOWER	1	\$ 678.00	\$ 678.00
7	FRONT BUMPER FOGLAMP COVER LH	1	\$ 159.00	\$ 159.00
8	FRONT BUMPER FOGLAMP LH	1	\$ 321.00	\$ 321.00
9	FRONT BUMPER REINFORCEMENT 399	1	\$ 651.00	\$ 651.00
10	FRONT BUMPER SPONGE	1	\$ 241.00	\$ 241.00
11	FRONT BUMPER CENTER BRACKET	1	\$ 211.00	\$ 211.00
12	FRONT BUMPER SIDE RETAINER	2	\$ 68.00	\$ 136.00
13	FRONT WIPER SIDE GARNISH LH	1	\$ 198.00	\$ 198.00
14	FRONT GRILLE 487.60	1	\$ 1,025.00	\$ 1,025.00
15	FRONT GRILLE LOGO	1	\$ 85.00	\$ 85.00
16	HEADLAMP 015mtg cm	2	\$ 3,521.00	\$ 7,422.00
17	HEADLAMP LOWER BRACKET	1	\$ 112.00	\$ 112.00
18	FRONT SUPPORT PANEL TOP GARNISH 166-30	1	\$ 312.00	\$ 312.00
19	FRONT SUPPORT PANEL 978	1	\$ 1,211.00	\$ 1,211.00
20	AIR CLEANER HOUSING	1	\$ 698.00	\$ 698.00
21	FRONT AIR DUCT	1	\$ 112.00	\$ 112.00
22	FRONT FENDER LH 645.10	1	\$ 898.00	\$ 898.00
23	FRONT FENDER INNER COWLING LH	1	\$ 284.00	\$ 284.00
24	FRONT FENDER ARCH LH	1	\$ 398.00	\$ 398.00
25	AIRCON CONDENSOR	1	\$ 1,120.00	\$ 1,120.00

03230.00

✓  
✓  
✓  
✓  
✓  
X  
X  
X  
✓  
✓  
X  
X  
✓  
✓  
✓  
✓  
✓  
✓  
X  
X  
✓

26	AIRCON SUCTION PIPE	Per 1	\$ 325.00	\$ 325.00	X
27	AIRCON DISCHARGE PIPE	Per 1	\$ 340.00	\$ 340.00	X
28	RADIATOR	Per 1	\$ 1,259.00	\$ 1,259.00	X
29	RADIATOR COWLING	Per 1	\$ 798.00	\$ 798.00	X
30	RADIATOR RESERVOIR	Per 1	\$ 298.00	\$ 298.00	X

TOTAL PRICE \$22,536.00  
 LESS 30% \$6,740.40  
**SUB TOTAL PRICE \$15,727.60**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIPS	10	\$ 6.50	\$ 20.00	✓
2	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00	X
5	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 20.00	✓
6	FRONT WHEEL ARCH GARNISH CLIPS	8	\$ 6.50	\$ 20.00	X
7	BONNET INSULATOR CLIP SET	1	\$ 50.00	\$ 50.00	X
8	FRONT FENDER COWLING CLIPS	18	\$ 6.50	\$ 20.00	X

**TOTAL \$180.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$1,200.00		60d
2	TO SPRAY PAINT AFFECTED AREA	\$1,200.00		80d
3	WIRING CHECK	\$80.00		20d
4	REMOVE AND REFIX FRONT SUPPORT PANEL	\$350.00		X
5	REFOCUS HEADLAMP BEAM	\$60.00		20d
7	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$120.00		100d
8	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$80.00		50d
9	RESEAT ENGINE LIGHT	\$350.00		X

**TOTAL**

**\$2,000.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$15,907.60  
 TOTAL LABOUR COST : \$2,000.00  
 TOTAL REPAIR COST : \$17,907.60

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: