

ASS. REC. BY:

REF:

LPC/23006841/kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

24 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

91700116

Date / Time

Action / Instruction

1/ 17A vehicle @ 40,132.00

Veh No:

SMU 2968 Yr Regn: 08, 2.0

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

C.C

1496

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

AU3 1324316

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

2.5/80R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

27/6/23

D.O.I.

7/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1) Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



TECH CHOON

AUTOMOTIVE PRIVATE LIMITED

Address: 60 Jalan Lam Huat #05-45, Carros Centre, Singapore 737869
Office: 6367 0710 Fax: 6368 8025 E-mail: tcawtl@singnet.com.sg

NOT Notarized

Repair After Paint 1 Day &

24 day,

LONPAC INSURANCE BHD
300, BEACH ROAD, #17-04/06
THE CONCOURSE
SINGAPORE 199555
ATTN: MOTOR CLAIMS DEPT

ESTIMATE REPAIR BILL

YOUR REF : GBC4141K
TYPE OF CLAIM : THIRD PARTY CLAIMS
CLAIMANT : CHIA KOK HENG
VEHICLE NO. : SMU2968E
MAKE/ MODEL : HONDA VEZEL
ACCIDENT DATE : 27/6/2023

MATERIAL COST

1	IPC	FRONT WINDSCREEN			
2	IPC	FRONT WINDSCREEN MOULDING			
3	IPC	LH FRONT WIPER ARM			
4	IPC	LH FRONT WIPER BLADE			
5	IPC	FRONT BUMPER COVER			
6	2 PCS	FRONT BUMPER RETAINERS			
7	6 PCS	FRONT BUMPER CLIPS			
8	IPC	FRONT BUMPER PDC SENSOR			
9	IPC	FRONT BUMPER PDC SENSOR HOLDERS			
10	IPC	FRONT BUMPER PDC SENSOR WIRE HARNESS			
11	IPC	LH FOG LAMP			
12	IPC	LH FOG LAMP BEZEL			
13	IPC	FOG LAMP HOLDER INNER			
14	IPC	FRONT BUMPER LOWER GRILLE			
15	IPC	FRONT BUMPER LOWER PAD			
16	IPC	FRONT BUMPER REINFORCEMENT			
17	IPC	FRONT BUMPER REINFORCEMENT TOP TRIM LH			
18	IPC	FRONT BUMPER REINFORCEMENT TOP TRIM RH			
19	3 PCS	FRONT BUMPER REINFORCEMENT TOP TRIM CLIPS			
20	IPC	FRONT AMBIENT SENSOR			
21	2 PCS	HEADLAMPS	<i>o/s my cm</i>	<i>n/s Brs</i>	
22	IPC	HEADLAMP CHROME LH			
23	IPC	HEADLAMP CHROME RH			
24	2 PCS	HEADLAMPS LOWER BRACKET			
25	IPC	LH FRONT FENDER			
26	IPC	RH FRONT FENDER			
27	IPC	LH FRONT FENDER DUST COVER			
28	12 PCS	FRONT FENDER DUST COVER CLIPS			
29	2 PCS	FRONT FENDER HYBRID EMBLEM			
30	IPC	FRONT GRILLE			
31	IPC	FRONT GRILLE CHROME			
32	IPC	FRONT GRILLE MID			
33	IPC	FRONT GRILLE LOGO			
34	IPC	FRONT LOGO BASE			
35	2 PCS	FRONT GRILLE SIDE INNER BRACKET			
36	IPC	BONNET			
37	IPC	BONNET RUBBER SEALS			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CM 2,514.25 ✓

RM 146.75 ✓

\$ 141.75 ✓

\$ 68.88 ✓

RM 626.63 ✓

CM 48.75 ✓

RM 44.18 ✓

\$ 250.00 ✓

\$ 100.00 ✓

\$ 137.50 ✓

\$ 381.75 ✓

\$ 41.75 ✓

\$ 68.88 ✓

Dr 433.88 ✓

Dr 134.25 ✓

RM 475.50 ✓

Dr 30.13 ✓

Dr 30.13 ✓

RM 22.09 ✓

\$ 369.75 ✓

o/s my cm *n/s Brs* 5,028.50 ✓

\$ 150.13 ✓

\$ 150.13 ✓

n/s cm 87.75 ✓

Br 479.25 ✓

R 479.25 ✓

Ta 146.75 ✓

RM 88.35 ✓

RM 137.75 ✓

mi 475.50 ✓

mi 266.00 ✓

mi 266.00 ✓

RM 37.63 ✓

mi 251.63 ✓

RM 98.25 ✓

Br 639.25 ✓

CM 31.38 ✓

38	1PC	BONNET INSULATOR	\$	CM	152.88	—
39	12 PCS	BONNET INSULATOR CLIPS	\$	M	88.35	—
40	2 PCS	BONNET HINGES	\$	M	100.25	—
41	1PC	BONNET LOCK	\$	M	122.63	—
42	1PC	BONNET LOCK BRACKET	\$	CM	138.00	—
43	3 PCS	BONNET LOCK BRACKER CLIPS	\$	M	22.09	—
44	1PC	FRONT SUPPORT PANEL	\$	M	802.13	—
45	1PC	FRONT SUPPORT PANEL TOP COVER	\$	M	75.13	—
46	10 PCS	FRONT SUPPORT PANEL TOP COVER CLIPS	\$	M	73.63	—
47	1PC	FRONT SUPPORT PANEL LOWER	\$		611.38	?
48	1PC	FRONT AIR INTAKE DUCT	\$	M	76.38	—
49	2 PCS	FRONT AIR INTAKE DUCT CLIPS	\$	M	14.73	—
50	1PC	FRONT AIR INTAKE HOSE	\$		63.88	?
51	1PC	AIR INTAKE LOWER DUCTING	\$		376.00	?
52	1PC	AIR RESONATOR	\$		225.13	?
53	1PC	INTAKE MANIFOLD	\$		507.63	?
54	1PC	INTAKEMANIFOLD VACUUM HOSE	\$		39.25	?
55	1PC	BATTERY POSITIVE TERMINAL	\$		251.75	?
56	1PC	AIR-CON CONDENSER	\$	M	710.13	✓
57	1PC	AIR-CON CONDSEER FAN COWLING	\$		123.25	?
58	1PC	AIR-CON CONDENSER FAN BLADE	\$		82.63	?
59	1PC	AIR-CON CONDENSER FAN MOTOR	\$		314.25	?
60	1PC	RADIATOR ASSY	\$		1,235.13	?
61	1PC	RADIATOR FAN COWLING	\$		123.25	?
62	1PC	RADIATOR FAN BLADE	\$		82.63	?
63	1PC	RADIATOR FAN MOTOR	\$		314.25	?
64	1PC	RADIATOR TOP HOSE	\$		44.13	?
65	1PC	REAR BUMPER	\$	M	714.25	—
66	1PC	REAR BUMPER LH REFLECTOR	\$	CM	185.13	—
67	1PC	REAR BUMPER RH REFLECTOR	\$	185.13	185.13	?
68	2 PCS	REAR BUMPER NUT	\$	M	15.00	—
69	1PC	REAR BUMPER LH SIDE PAD	\$	M	150.13	—
70	1PC	REAR BUMPER RH SIDE PAD	\$		150.13	?
71	1PC	REAR BUMPER CLIPS	\$	M	58.90	—
72	1PC	REAR UNDER LOWER GARNISH	\$	CM	238.00	—
73	1PC	RH REAR FENDER	\$	Bu	1,264.25	—
74	1PC	LH REAR FENDER	\$	Bu	1,264.25	—
75	1PC	LH REAR FENDER DUST COVER	\$	Reform	277.25	—
76	1PC	LH REAR FENDER ARCH TRIM	\$	M	146.38	—
77	1PC	RH FENDER REAR DUST COVER	\$	M	277.25	—
78	8 PCS	RH FENDER REAR DUST COVER CLIP	\$	M	60.00	X
79	8 PCS	LH FENDER REAR DUST COVER CLIP	\$	M	60.00	X
80	1PC	RH REAR FENDER ARCH TRIM	\$	M	146.38	X
81	1PC	RH REAR FENDER AIR POCKET	\$	M	225.38	X
82	1PC	LH TAIL LAMP	\$	Bu	536.38	—
83	2 PCS	TAIL LAMP HOLDER	\$	M	20.00	—
84	1PC	RH TAIL LAMP	\$	Bu	536.38	—
85	1PC	REAR WINDSCREEN	\$	Shatter	1,067.00	—
86	2 PCS	REAR WINDSCREEN MOULDING	\$	M	375.75	—
87	1PC	TAIL GATE ASSY	\$	M	1,139.25	—
88	2 PCS	TAIL GATE ABSORBER	\$		662.75	?
89	1PC	REAR BUMPER RETAINER LH	\$	CM	68.88	—
90	1PC	REAR BUMPER RETAINER RH	\$	CM	68.88	—
91	1PC	TAIL GATE VEZEL EMBLEM	\$	M	63.00	—
92	1PC	TAIL GATE HYBRID EMBLEM	\$	M	64.25	—
93	1PC	TAIL GATE SPOILER	\$		639.25	?
94	1PC	TAILGATE RH REFLECTOR	\$	Bu	561.38	—
95	1PC	TAILGATE LH REFLECTOR	\$	CM	555.13	—
96	1PC	TAILGATE OUTER GARNISH	\$	M	294.25	—
97	6 PCS	TAILGATE OUTER GARNISH CLIP	\$	M	45.00	—
98	1PC	TAILGATE OUTER GARNISH "H" LOGO	\$	M	31.63	—
99	1PC	TAILGATE INNER LOCK	\$	M	146.75	—
100	1PC	TAILGATE INNER LOCK STRIKER CABLE	\$	M	276.00	—

101	1PC	TAILGATE INNER PULL PULL POCKET COVER
102	1PC	TAILGATE INNER TRIM BOARD MAIN
103	1PC	TAILGATE INNER TRIM BOARD LH
104	1PC	TAILGATE INNER TRIM BOARD RH
105	1PC	TAILGATE INNER TRIM BOARD UPPER
106	2 PCS	TAILGATE HINGES
107	1PC	TAILGATE W/STRIP
108	2 PCS	REAR NUMBER PLATE LAMP
109	1PC	REAR WIPER BLADE
110	1PC	REAR WIPER ARM
111	1PC	REAR WIPER ARM COVER
112	1PC	REAR WIPER MOTOR
113	1PC	REAR ANTENNA
114	1PC	HYBRID BATTERY PACK
115	1PC	HYBRID BATTERY CASING TOP
116	1PC	HYBRID BATTERY CASING LOWER
117	1PC	HYBRID BATTERY AIR DUCT
118	1PC	REAR END PANEL <i>P-?</i>
119	1PC	REAR END PANEL INNER TRIM
120	3 PCS	REAR END PANEL INNER TRIM CLIPS
121	1PC	REAR FLOOR PANEL
122	1PC	REAR FLOOR TOOL TRAY
123	1PC	REAR END PANEL INNER TRIM - LH
124	1PC	REAR FENDER INNER TRIM LH UPPER
125	1PC	REAR FENDER INNER TRIM RH UPPER
126	1PC	REAR FENDER INNER TRIM RH
127	16 PCS	REAR FENDER INNER TRIM CLIPS
128	1PC	REAR EXHAUST MUFFLER
129	1PC	REAR EXHAUST MUFFLER HEAT SHEILD
130	2 PCS	REAR EXHAUST MUFFLER MOUNTING
131	1PC	MID EXHAUST PIPE
132	2 PCS	MID EXHAUST PIPE MOUNTING
133	1PC	REAR LH TIRE
134	1PC	REAR RH TIRE
135	2 PCS	RR SHOCK ABSORBER
136	2 PCS	RR SHOCK ABSORBER TOP MOUNTING

LESS : DISCOUNT 20%

\$	150.50	7
\$	238.00	✓
\$	68.88	✓
\$	68.88	7
\$	154.25	7
\$	165.25	✓
\$	147.00	✓
\$	115.75	✓
\$	72.88	✓
\$	82.63	✓
\$	47.63	✓
\$	256.75	✓
\$		
\$	11,809.88	7
\$	361.13	7
\$	252.25	7
\$		
\$	1,096.38	✓
\$	146.75	✓
\$	22.09	✓
\$	983.88	7
\$	573.88	7
\$	400.13	✓
\$	360.88	7
\$	360.88	X
\$	400.13	7
\$	117.80	7
\$	724.25	7
\$	58.88	7
\$	75.25	7
\$	874.13	7
\$	75.25	7
\$	350.00	9061m
\$	350.00	X
\$	1,444.00	
\$	805.25	
\$		
\$	11,819.64	
\$	47,278.55	

S/Nett Items

1	1 PC	FRONT WINDSCREEN SEALANT
2	1 PC	FRONT WINDSCREEN INNER SEAL
3	1 PC	"1U" BRACKET
4	1 PC	FRONT NUMBER PLATE
5	1 BTL	RADIATOR COOLANT
6	1 PC	REAR BUMBER PLATE
7	1 PC	REAR W/ SCREEN SEALANT
8	1 PC	REAR W/ INNER SCREEN SEALANT
9	1 SET	REVERSE SENSOR
10	2 SET	REVERSE CAMERA
11	3 SET	REAR CAMERA

\$	40.00	✓
\$	20.00	✓
\$	28.00	✓
\$	35.00	✓
\$	40.00	✓
\$	35.00	✓
\$	40.00	✓
\$	20.00	✓
\$	220.00	2001m
\$	700.00	7
\$	600.00	7
\$	1,778.00	

LABOUR CHARGE :

FRONT			
1	TO REPLACE FRONT WINDSCREEN	\$	400.00 1201
2	R/A AIR-CON AND RECHARGE GAS	\$	180.00 1001
3	TO REPLACE AIR INTAKE MANIFOLD	\$	100.00 7
4	TO REPLACE BATTERY POSITIVE TERMINAL AND CONDUCT FINAL TESTING	\$	120.00 ✓

5	TO REMOVE DAMAGED PARTS AND ATTACHMENT, PANEL BEAT AND REPAIR RH FRONT FENDERS, FRT INNER PANEL AND FRT CHASSIS RAIL. CUTTING/ WELDING AND REPLACE FRONT END DAMAGED BODY PARTS.	\$	3,000.00	900-1200/
6	TO SPRAY PAINTING FRT BUMPER, BONNET, BOTH FRONT FENDERS, FRONT INNER PANELS	\$	1,500.00	1000/
REAR				
1	REPLACE REAR WINDSCREEN	\$	250.00	120/
2	R/I BOOT INTERIOR TRIM, SEATS, CARPETING ETC.	\$	350.00	100/
3	R/I FUEL TANK	\$	400.00	60/
4	R/I REAR SUSPENSION AND UNDERCARRIAGE	\$	380.00	200/
5	REMOVE DAMAGED PARTS AND ATTACHMENTS, PANEL BEAT AND REPAIR REAR WHEEL HOUSING PANELS, CHASSIS FRAME, SIDE PANELS, RH REAR FENDER. CUTTING/WELDING AND REPLACE REAR END DAMAGED BODY PARTS.	\$	5,800.00	2400/
6	SPRAY PAINTING- RR BUMPER SIDE PADS, TAILGATE, BOTH REAR FENDERS TAILGATE, REAR END PANEL, REAR FLOOR PANEL AND REAR INNER PANEL	\$	2,500.00	1400/
OTHERS				
1	RECOVER AND TOWING CHARGES	\$	(Bill) 120.00	?
2	ISOLATE AND REMOVE HYBRID BATTERY SUPPLY SYSTEM. REPLACE HYBRID BATTERY PACK AND CONDUCT FINAL TESTING	\$	2,500.00	?
3	TO MOUNT VEHICLE ON BENCH TO CARRY OUT CHASSIS ALIGNMENT REPAIRS	\$	180.00	?
4	RUSTPROOFING	\$	250.00	210/
5	RESET ECU	\$	200.00	?
6	RESET WHEEL ALIGNMENT	\$	150.00	60/
7	SUPPLY AND INSTALL FRONT AND REAR WINDSCREEN SOLAR FILM	\$	450.00	?
		\$	67,886.55	
	GST 8%:	\$	5,430.92	
		\$	<u>73,317.47</u>	

TOH AH SWEE SPRAY PAINTING CO.
WEI SI (TEL: 63660286)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/06/2023 18:15 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	27/06/2023 08:25 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SLE (TOWARDS WOODLANDS) NEAR MANDAI DEPOT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMU2968E
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHIA KOK HENG
NRIC No	SXXXX592J
Email Address	ROGERCHIAKH@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-97616708
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezel
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10602696R01

DRIVER

Name of Driver	CHIA KOK HENG
NRIC No	SXXXX592J
Date Of Birth	14/02/1976
Occupation	Indoor


Budget Direct
Vehicle: SMU 2968E
28/06/2023

SKETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA, to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Sketch Plan



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



WILLIAMSON COMPANY