

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd  
6 Raffles Quay  
#22-00  
Singapore 048580From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Priya

Date: 07 Jul 2023

**Preliminary Advice**

Vehicle No	: SMF3584B	Accident Date	: 23/06/2023
Make	: NISSAN X-TRAIL	Policy No.	: D20MFL0000326_02
Assignment Date	: 06/07/2023	Excess	: S\$0.00
Date of Inspection	: 7/7/2023	Est. Duration of Repair	: 2
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,675.30
Revised Amount	:S\$	4,001.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,001.40

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	36,325.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,675.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Part by part repair

Please note that the preliminary advise amount (Revised &amp; Check items) stated are subject to consistency check, part prices and labour cost .