

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claim \$ No. _____

Sum Insured: _____

Excess: \$600/2

(Client Record) _____

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$98K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFP 281J Yr Regn: 28/2/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 318i c.c. 1499

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: ? T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA8E36090N482416

Gen. Cond: Good (Fair) / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 30/6/2023 D.O.I. 18/7/2023

Survey held at: Desk Top Survey

Des. of Damages: (Frt) / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Net Value \$52,424.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

> Back to OneMotoring

D.O.A. : 30/6/2023
Bal. : 4 yrs 7.9 months
M.V. : \$98,000

Enquire PARF/COE Rebate for Registered Vehicle


Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	659H
Vehicle Details	
Vehicle No.:	SFP218J
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jul 2023
Vehicle Make:	B.M.W.
Vehicle Model:	318i LED NAV
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	36475115B38B15A
Chassis No.:	WBA8E36090NU82416
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,947.00
Original Registration Date:	28 Feb 2018
First Registration Date:	28 Feb 2018
Transfer Count:	①
Actual ARF Paid:	\$39,526.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2028
PARF Rebate Amount:	\$27,668.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$17,908.00
Total Rebate Amount:	\$45,576.00

The information contained herein is correct as at 18 Jul 2023

N.V. : \$52,424.

OK

17,000



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000964955-01	Date of Loss:	30/06/2023
Vehicle Reg. No.:	SFP218J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHUA BOON KEONG		
Make/Model:	BMW 318I, 1.5 (A)	Vehicle Reg. Date:	28/02/2018
Vehicle Colour:	WHITE	Chassis No:	WBA8E36090NU82416
Engine No:	36475115B38B15A		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 3		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	5,549.50
Miscellaneous Items	0.00
Labour	1,310.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,859.50
+ GST 8.00% (\$\$)	548.76
Nett Amount (\$\$)	7,408.26

This claim is handled by: JUNIOR

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG

Version: 1.0 (Last Synchronised: 06 Jul 2023)

Parts: 143

BMW 318I 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/SFP218J/06/07/2023 16:24**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT HEADLAMP LH	0.00	0.00	*2,900.00 F	CUT
2	1		*FRONT BUMPER	0.00	0.00	*950.00 F	DD
3	1		*FRONT BUMPER LOGO	0.00	0.00	*90.00 F	NEC
4	1		*FRONT BUMPER SENSOR (CENTER)	0.00	0.00	*230.00 F	
5	1		*FRONT BUMPER SENSOR (OUTER)	0.00	0.00	*230.00 F	CUT
6	1		*FRONT FOGLAMP LH (CEHCK)	0.00	0.00	-	?
7	1		*FRONT FOGLAMP COVER LH	0.00	0.00	*80.00 F	?
8	1		*FRONT FOGLAMP COVER CHROME LH	0.00	0.00	*95.00 F	CUT
9	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*170.00 F	SRA
10	1		*FRONT BUMPER LOWER GRILLE CHROME	0.00	0.00	*120.00 F	?
11	1		*FRONT BUMPER RETAINER LH	0.00	0.00	*25.00 F	?
12	1		*FRONT BUMPER SPONGE	0.00	0.00	*95.00 F	?
13	1		*FRONT FOGLAMP BRACKET LH	0.00	0.00	*60.00 F	?
14	1		*FRONT HEADLAMP PANEL LH - CHECK	0.00	0.00	-	?

F=Franchise part.

Sub Total (\$\$)

5,045.00

+ Margin on L,N Items 10.00% (\$\$)

504.50

Total Parts (\$\$)

5,549.50

Mova Automotive Pte Ltd/SFP218J/06/07/2023 16:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPAIR FRONT FENDER LH, TO REMOVE & REPLACE ACCIDENT DAMAGED PARTS & REALIGN AFFECTED AREAS	New	350.00 200
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	450.00 250
3	TO REMOVE & REFIX FRONT SENSOR & CHECKING WIRING	New	80.00 50
4	TO REMOVE & REPLACE FRONT HEADLAMP & CHECK HEADLIGHT FOCUS	New	80.00 30
5	TO DIGNOSE & REPROGRAMEE AFTER REPAIR	New	350.00 X
Gross Labour Cost (S\$)			1,310.00

Mova Automotive Pte Ltd/SFP218J/06/07/2023 16:24. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

- Not authorise.

- Excess = \$600/-

- P/S or L/S repair.?

- Resurvey before paint for P/P repair.

- Survey by Simon. (6256 3561).

Repairer, please read.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: