

ASS. REC. BY:

REF:

EGW 2300 6896/Kny3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 44K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNL 9292K Yr Regn: 10.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota A/T/S

C.G. 1598

Colour

B. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

117593

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH104539464

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Kumho 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

2/7/23

D.O.I.

7/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/7/21 Rm @ 2100L Carport (Red. \$ 5745. 73%)

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896

HP: 93911482

Estimation

Date:

4/7/2023

Vehicle:

SNL9292K

Make / Model:

TOYOTA ALTIS

Not Notarised
11km @ 2100ph
Running after painting
4 days

No.	Description	Unit	Unit Price	Amount
1	BOOTLID WEATHERSTRIP <i>pu</i>	1	\$ 212.00	\$ 212.00
2	TAILAMP RH <i>pu</i>	1	\$ 612.00	\$ 612.00
3	REAR BUMPER <i>515.70 BUL</i>	1	\$ 798.00	\$ 798.00
4	REAR BUMPER SIDE RETAINER RH <i>bul</i>	1	\$ 112.00	\$ 112.00
5	REAR BUMPER BRACKET RH <i>bul</i>	1	\$ 168.00	\$ 168.00
6	REAR BUMPER SENSOR <i>pu</i>	2	\$ 381.00	\$ 762.00
7	REAR BUMPER REINFORCEMENT <i>bul</i>	1	\$ 395.00	\$ 395.00
8	REAR BUMPER REFLECTOR RH <i>cm</i>	1	\$ 112.00	\$ 112.00
9	REAR BUMPER UNDERCOVER <i>pu</i>	1	\$ 315.00	\$ 315.00
10	REAR FENDER RH <i>pu</i>	1	\$ 698.00	\$ 698.00
11	REAR FENDER COWLING <i>pu</i>	2	\$ 358.00	\$ 716.00
12	REAR END PANEL <i>bul</i>	1	\$ 695.00	\$ 695.00
13	END PANEL TOP GARNISH <i>pu</i>	1	\$ 278.00	\$ 278.00
14	REAR FLOOR PANEL SIDE RH <i>pu</i>	1	\$ 312.00	\$ 312.00
15	REAR SPARE TYRE TOP BOARD <i>pu</i>	1	\$ 357.00	\$ 357.00
16	REAR EXHAUST PIPE HEAT SHIELD <i>pu</i>	1	\$ 398.00	\$ 398.00
				\$ 6,940.00
			Less 25%	\$ 1,735.00
			Total	\$ 5,205.00

S/Nett items:				
1	TAILAMP CLIPS SET <i>nn</i>	1	\$ 40.00	\$ 40.00
2	REAR FENDER COWLING CLIPS SET	1	\$ 50.00	\$ 50.00
3	REAR END PANEL TOP GARNISH CLIPS	1	\$ 30.00	\$ 30.00
4	REAR END PANEL SEALANT <i>nn</i>	1	\$ 120.00	\$ 120.00
5	REAR BUMPER CLIPS	1	\$ 50.00	\$ 50.00
				\$ 290.00
Labour to: Rear				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
3	REMOVE AND REFIR REAR UPHOLSTERY, SEAT ETC..	1	\$ 300.00	\$ 300.00
4	REMOVE AND REFIR REAR BUMPER SENSOR	1	\$ 100.00	\$ 100.00
5	REAR CHASSIS ALIGNMENT RH	1	\$ 200.00	\$ 200.00
6	TO CHECK ELECTRICAL WIRING	1	\$ 100.00	\$ 100.00
7	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 50.00	\$ 50.00
				\$ 2,350.00
Parts Replacement Amount			\$	5,495.00
Total Amount for Labour			\$	2,350.00

	Total Amount	\$ 7,845.00
--	--------------	-------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental work must be approved and is subject to prior approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: