

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 14 Jul 2023

**Preliminary Advice**

Insured Vehicle No	: SLM3880X	Accident Date	: 30/06/2023
TP Vehicle No	: SJT952D	Assignment Date	: 07/07/2023
Make	: CHEVROLET CRUZE	Est. Duration of Repair	: 2
Date of Inspection	: 11/07/2023		
Inspection At	: HUAT HOCK MOTOR WORKSHOP (HQ) BLK 3012 BEDOK NORTH AVE 4, #01-2054 BEDOK INDUSTRIAL PARK E SINGAPORE 1648		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,590.80
Revised Amount	:S\$	2,377.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,377.20

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.