



Your Ref: S3M04K0E

Date: 13<sup>th</sup> July 2023

Our Ref: CS3/HSB23002183/Rqp3e2-1

**M/s HSBC Life (Singapore) Pte Ltd**

10 Marina Boulevard  
#48-01 Marina Bay Financial Centre Tower 2  
Singapore 018983  
(The Motor Claims Department)

Attn: Low Garnet

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBC 777C  
INSURED VEHICLE: SHC 3775S  
ACCIDENT DATE: 25/02/2023**

We thank you for your instruction on 20/06/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBC 777C from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicles GBC 777C and SHC 3775S.
- c) Final Repair Bill of GBC 777C from M/s Koh Kock Leong Construction Pte. Ltd.
- d) Colour damaged vehicle photographs of GBC 777C.

Pre-Repair Inspection Date: 01/03/2023 at M/s No. 24 Tuas Avenue 2, Repairer: Koh Kock Leong Enterprise PL.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBC 777C  
Make & Model : Land Rover Defender 90 2.4L Puma  
Year of Registration : 2009  
Chassis Number : SALLDVAS79A768842  
Engine Capacity : 2402 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.