

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 07 Jul 2023)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD4682P/07/07/2023 16:19**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	de ✓ *459.40 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	ue ✓ *22.00 FL
3	1		*REAR BUMPER BEAM	20.00	0.00	ue ✓ *394.80 FL
4	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de ✓ *451.25 FL
5	1		*REAR FOG LAMP ASSY	20.00	0.00	cut ✓ *201.50 FL
6	1		*ANTENNA SMARTKEY	20.00	0.00	ue ✓ *40.50 FL
7	1		*REAR BUMPER TOW COVER	20.00	0.00	de ✓ *98.80 FL
8	1		*BOOTLID COVER	20.00	0.00	ue ✓ *2,549.70 FL
9	1		*BOOTLID EMBLEM - IONIQ	20.00	0.00	ue ✓ *31.30 FL
10	1		*BOOTLID EMBLEM - HYBRID	20.00	0.00	ue ✓ *24.30 FL
11	1		*BOOTLID EMBLEM - H	20.00	0.00	cut ✓ *28.00 FL
12	1		*BOOTLID GLASS LOWER MOULDING	20.00	0.00	ue ✓ *145.20 FL
13	1		*BOOTLID GLASS UPPER MOULDING	20.00	0.00	ue ✓ *186.30 FL
14	1		*REAR NUMBER PLATE	0.00	0.00	ue ✓ *55.00 F
15	1		*REAR BOOTLID COMFORT LOGO	0.00	0.00	ue ✓ *30.00 F
16	1		*REAR BOOTLID COMFORT TEL NOS. LOGO	0.00	0.00	ue ✓ *30.00 F
17	1		*REAR BOOTLID APPS LOGO	0.00	0.00	ue ✓ *40.00 F
18	1		*REAR WINDSCREEN SEALANT	0.00	0.00	ue ✓ *46.00 F
19	1		*REVERSE SENSOR	0.00	0.00	ue ✓ *180.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,014.05
- List Item Discount on L Items (\$\$)	926.61
Total Parts (\$\$)	4,087.44

ComfortDelGro Engineering Pte Ltd/SHD4682P/07/07/2023 16:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

4197.75
20% = 3358.20
SN 381

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	525 1,100.00
2	SPRAY PAINT	New	500 600.00
3	CHECK WIRING	New	30 50.00
4	TUFF KOTE	New	30 50.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	✓ 120.00
6	REMOVE/REFIX REVERSE SENSOR	New	30 50.00
7	TOWING CHARGE	New	✓ 60.00
Gross Labour Cost (S\$)			1295 2,030.00

ComfortDelGro Engineering Pte Ltd/SHD4682P/07/07/2023 16:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanji 97495749
 with 1270 5 pm
 03 days
 1/5 resurvey after repair
 tanji e/khauto-wa

3358.20
 381
 11
 1295
 5045.20
 484050
 03 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "no prejudice" basis
- No illegal
- Subprime is subject

Signature: _____
 Date: _____