

#### **CARWORKZ SG PTE LTD**

10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645 H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua) Co. Reg. No: 202039874Z GST No: 202039874Z

Email: carworkzws@gmail.com

Not Notherh 45 Why & Menny After Pains

ESTIMATED REPAIR COST DETAILS

ACC-23-0036

To:

**HSBC LIFE (SINGAPORE) PTE LTD** 

**ROBINSON ROAD POST OFFICE P.O. BOX 1538** 

**SINGAPORE 903038** 

Date: 09/07/2023

Vehicle No.: FBH-6608-S

Make: HONDA Model: CBR400R M

**Attention:** Motor Claim Department

Attention: Motor Claim Department				
QTY	DESCRIPTION	REPAIR AMOUNT SURVEYOR APP.		
<u>List Item</u>				
1	COWLING, FRONT	CM \$360.00		
1	HEADLIGHT ASSY	CM 61,620.00		
1	COVER LOWER, HEADLIGHT ASSY	CM \$290.00 —		
1	FENDER, FRONT	CM \$240.00 —		
1	FORK ASSY LH	\$1,280.00		
1	FORK ASSY RH	\$1,280.00		
1	UNDERBRACKET, FORK	\$630.00		
1	BEARING, STEERING KIT	\$150.00		
1	CAST WHEEL, FRONT	ns \$960.00		
1	SHAFT, CAST WHEEL	\$140.00 X		
1	BEARING, CAST WHEEL	\$50.00		
1	DISC, BRAKE FRONT	\$190.00 X		
1	COWLING SIDE, FRONT LH	EM \$680.00 -		
1	COWLING SIDE, FRONT RH	Feec \$680.00 X		
1	AIR GUIDE, COWLING SIDE FRONT	na \$190.00 <u></u>		
1	SIGNAL LIGHT, FRONT LH	em \$160.00 —		
1	AIR INTAKE, LH	\$390.00 <u> </u>		
1	FUEL TANK	★ \$2,600.00  ★		
1	COWLING INNER, SIDE, FRONT LH	cm \$460.00 —		
1	COVER, SIDE CENTRE LH	\$310.00		
1	COVER, ENGINE LH	nd \$185.00 —		
1	GASKET, ENGINE COVER LH	Ma \$30.00 —		
1	LEVER, GEAR	<b>3</b> \$90.00 —		
1	RUBBER, LEVER GEAR	M \$15.00 —		
1	BRACKET, FOOTREST FRONT LH	\$180.00		



# **CARWORKZ SG PTE LTD**

10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645 H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua) Co. Reg. No: 202039874Z GST No: 202039874Z Email: carworkzws@gmail.com

### **ESTIMATED REPAIR COST DETAILS**

\$50.00 15/

			ACC-23-0036	
1	FOOTREST, FRONT LH	<b>19</b> \$75.00	<u> </u>	
1	RUBBER, FOOTREST FRONT LH	Gy \$30.00	_	
1	BRACKET REAR, FOOTREST LH	\$165.00	7	
1	FOOTREST, REAR LH	nes \$45.00		
1	SIDE STAND	\$90.00	X	
1	COVER SIDE, REAR LH	\$305.00	X	
1	SIGNAL LIGHT, REAR LH	cnn \$160.00		
1	FENDER, REAR, LICENSE PLATE	\$220.00	X	
1	EXHAUST MUFFLER	<b>\$1,500.00</b>	<b>X</b>	
1	PROTECTOR, EXHAUST MUFFLER	n \$160.00	×	
1	GASKET, EXHAUST MUFFLER	<i>1</i> \$40.00	X	
	Sub Total	\$15,950.00		
	Discount 10% on Parts	(\$1,595.00)		
`		\$14,355.00		
Special Nett				
1	MIRROR STEALTH TYPE, LH	Res \$145.00	ā	
1	MIRROR STEALTH TYPE, RH	m \$145.00	<b>X</b>	
1	LEVER, CLUTCH	nu \$120.00	_	
1	GRIP HANDLE LH	nd \$50.00	_	
1	BALANCER, HANDLE LH	14 \$60.00	_	
1	USB CHARGER	مر \$120.00	X	
1	HOLDER, HANDPHONE	n \$90.00	<b>X</b>	
1	BAR, HANDLE VORTEX LH	Ry \$320.00		
1	NUMBER PLATE, REAR	By \$20.00	125m	
1	TYRE, BRIDGESTONE BATTLAX T32 120/70ZR17	\$190.00	7	
	Sub Total	\$1,260.00		
		<b>7-7-</b> 00:00	1	
Labour & Misc				
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$800.00	2501	
	TO CONDUCT FORK ALIGNMENT	\$120.00	<u></u>	
	TO CONDUCT SUBFRAME ALIGNMENT	\$480.00	7	
			I	

TO RECONNECT ALL WIRINGS



## **CARWORKZ SG PTE LTD**

10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645 H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua) Co. Reg. No: 202039874Z GST No: 202039874Z Email: carworkzws@gmail.com

#### **ESTIMATED REPAIR COST DETAILS**

ACC-23-0036

TO PERFORM ELECTRICAL CHECK **Sub Total** 

12 \$30.00 X \$1,480.00

**Sub Total** 

\$17,095.00

**GST 8%** 

\$1,367.60

**Total** 

\$18,462.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: