


(08/11/13) Web
ASS. REC. BY: *[Signature]*

REF: CS/SMR 23007011/RVY3

8394

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: *SHA 9358J*
at Workshop m/s *DINH AUTOMOTIVE*
of *31, CORPORATION RD*
Insured: *SMR*
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *23K*
IDAC/Accident Rpt: Consistent? : Yes or No
GIA / PR. Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SHA 9358J* Yr Regn: *2017* *MD*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: *TOYOTA PRIUS* *HYBRID* *1800* c.c. *1798*
Colour: *YELLOW* A/C: Insured / Std / NI / NA
Sp. Reading: *828154* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *3TDKB30F4903561309*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: NI / S/Rim / STD A/Rim or
Tyre Size: F: *195/65R15*
R: *4.*
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *TRIANGLE*
Front Rear
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. *10/07/23* D.O.I. *11/07/23*
Survey held at *DINH AUTO*
Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
REPAIR LIMIT- 10K

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report
1) _____
Date/Time, File Return to? _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Survey Fee: _____
Transportation: _____
S + RS, SI _____
Photos _____
Others _____
TOTAL _____

Report Format : _____
Lump Sum / I.B.I: (\$) _____

Add Fee: ☐ : Site Insp (\$) _____
☐ : Interview (\$) _____
☐ : Tech. Invs (\$) _____
☐ : Weekend (\$) _____

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

11/07/2023 11:55

JOB-NO: 50115265

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 4

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA9358J

TRANS: AUTO

CHASSIS: JTDKB3FU903561309

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZRS056101

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREAS	1.00	3,000.00	0.00	3,000.00	7	Y	1800
2 TO RUST PROOFING OF AFFECTED AREAS	1.00	210.00	0.00	210.00		Y	100
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	1.00	300.00	0.00	300.00		Y	150
4 TO DIAGNOSTIC, CHECK WIRING, LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	250.00	0.00	250.00		Y	100
5 TO TRANSFER REAR BOOT MECHANISM TO NEW BOOT AND PERFORM WATER SEEPAGE TEST	1.00	150.00	0.00	150.00		Y	60
6 TO CHECK AND REPAIR WIRE HARNESS	1.00	150.00	0.00	150.00		Y	\$X
7 TO REFIT REAR REVERSE SENSOR	1.00	100.00	0.00	100.00		Y	40
8 TO REMOVE AND REFIT REAR TAILGATE UPPER AND LOWER WINDSCREEN GLASS TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00		Y	180
9 TO REMOVE AND REFIT REAR EXHAUST TO ENABLE BODYWORK REPAIR	1.00	150.00	0.00	150.00		Y	60?
10 MOUNT WORKBENCH - TO REALIGNMENT CHASSIS AND ACCIDENT AFFECTED AREA	1.00	450.00	0.00	450.00		Y	?200?
11 TO VACUUM AND TOPUP A/C GAS	1.00	120.00	0.00	120.00	100	Y	100?
12 TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00		Y	100?
13 TO READJUST AND REALIGN HEADLAMP AIM	1.00	100.00	0.00	100.00		Y	30
14 TO RESPRAY REAR BUMPER COVER	1.00	250.00	0.00	250.00		Y	200
15 TO RESPRAY REAR BUMPER EXTENSION FILLER	1.00	250.00	0.00	250.00		Y	X
16 TO RESPRAY REAR REVERSE SENSOR	1.00	250.00	0.00	250.00		Y	X
17 TO RESPRAY REAR TAILGATE PANEL	1.00	250.00	0.00	250.00		Y	200
18 TO RESPRAY REAR TAILGATE OUTER GARNISH	1.00	250.00	0.00	250.00		Y	100
19 TO RESPRAY REAR TAILGATE SPOILER	1.00	250.00	0.00	250.00		Y	X
20 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	X
21 TO RESPRAY REAR FLOOR PAN & EXTENSION	1.00	250.00	0.00	250.00		Y	200?
22 TO RESPRAY REAR LH QUARTER PANEL	1.00	250.00	0.00	250.00		Y	X
23 TO RESPRAY REAR RH QUARTER PANEL	1.00	250.00	0.00	250.00		Y	X
24 TO RESPRAY ROOF PANEL	1.00	250.00	0.00	250.00		Y	100
25 TO RESPRAY FRONT BUMPER COVER	1.00	250.00	0.00	250.00		Y	200

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
26 TO RESPRAY FRONT BUMPER TOWING COVER	1.00	250.00	0.00	250.00		Y	X
27 TO RESPRAY FRONT LH FENDER PANEL	1.00	250.00	0.00	250.00		Y	X
28 TO RESPRAY FRONT RH FENDER PANEL	1.00	250.00	0.00	250.00		Y	X
29 TO RESPRAY FRONT RADIATOR SUPPORT PANEL	1.00	250.00	0.00	250.00		Y	7,200?
30 TO RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00		Y	200
31 TO RESPRAY FRONT BONNET HINGE	1.00	250.00	0.00	250.00		Y	X
TOTAL:		10,000.00	0.00	10,000.00			
MATERIALS							
1 REAR BUMPER <i>de</i>	1.00	442.60	110.65	331.95	L	Y	
2 REAR BUMPER CENTER GUARD <i>de</i>	1.00	576.30	144.08	432.22	L	Y	
3 REAR BUMPER REINFORCEMENT <i>?</i>	1.00	332.70	83.18	249.52	L	Y	
4 REAR LH BUMPER RETAINER <i>re</i>	1.00	116.50	29.13	87.37	L	Y	
5 REAR RH BUMPER RETAINER <i>re</i>	1.00	117.70	29.43	88.27	L	Y	
6 REAR BUMPER TOWING COVER <i>X</i>	1.00	15.40	3.85	11.55	L	Y	
7 REAR BUMPER CENTER UNDER COVER <i>X</i>	1.00	229.90	57.48	172.42	L	Y	
8 REAR LH BUMPER UNDER COVER <i>X</i>	1.00	241.90	60.48	181.42	L	Y	
9 REAR RH BUMPER UNDER COVER <i>X</i>	1.00	175.10	43.78	131.32	L	Y	
10 REAR LH BUMPER EXTENSION FILLER <i>X</i>	1.00	123.70	30.93	92.77	L	Y	
11 REAR RH BUMPER EXTENSION FILLER <i>X</i>	1.00	123.70	30.93	92.77	L	Y	
12 REAR EXHAUST TAIL PIPE <i>X</i>	1.00	1,649.00	412.25	1,236.75	L	Y	
13 REAR EXHAUST TAIL PIPE GASKET <i>X</i>	1.00	53.50	13.38	40.12	L	Y	
14 REAR EXHAUST HEAT SHIELD <i>X</i>	1.00	141.00	35.25	105.75	L	Y	
15 SMART KEY ANTENNA <i>X</i>	1.00	72.00	18.00	54.00	L	Y	
16 REAR TAILGATE PANEL ASSY <i>lt</i>	1.00	1,147.80	286.95	860.85	L	Y	
17 REAR TAILGATE OUTER GARNISH <i>sen</i>	1.00	925.60	231.40	694.20	L	Y	
18 REAR TAILGATE TOYOTA EMBLEM <i>re</i>	1.00	47.90	11.98	35.92	L	Y	
19 REAR TAILGATE PRIUS EMBLEM <i>re</i>	1.00	54.60	13.65	40.95	L	Y	
20 REAR TAILGATE HYBRID EMBLEM <i>re</i>	1.00	54.60	13.65	40.95	L	Y	
21 REAR BOOT WEATHERSTRIP <i>re</i>	1.00	372.30	93.08	279.22	L	Y	
22 REAR BOOT LOCK <i>?</i>	1.00	467.00	116.75	350.25	L	Y	
23 REAR BOOT INNER TRIM BOARD (BIG) <i>?</i>	1.00	259.20	64.80	194.40	L	Y	
24 REAR TAILGATE UPPER WINDSCREEN ADHESIVE DAM <i>re</i>	1.00	28.90	7.23	21.67	L	Y	
25 REAR TAILGATE UPPER WINDSCREEN MOULDING <i>re</i>	1.00	35.50	8.88	26.62	L	Y	
26 REAR TAILGATE LOWER WINDSCREEN MOULDING <i>re</i>	1.00	23.60	5.90	17.70	L	Y	
27 REAR TAILGATE LOWER WINDSCREEN ADHESIVE DAM <i>re</i>	1.00	28.90	7.23	21.67	L	Y	
28 REAR LH TAILGATE LOWER WINDSCREEN MOULDING NO.2 <i>re</i>	1.00	30.90	7.73	23.17	L	Y	
29 REAR RH TAILGATE LOWER WINDSCREEN MOULDING NO.2 <i>re</i>	1.00	30.90	7.73	23.17	L	Y	
30 REAR LH TAILGATE HINGE <i>X</i>	1.00	61.00	15.25	45.75	L	Y	
31 REAR RH TAILGATE HINGE <i>X</i>	1.00	61.00	15.25	45.75	L	Y	
32 REAR LH TAILGATE STRUT <i>X</i>	1.00	242.50	60.63	181.87	L	Y	
33 REAR RH TAILGATE STRUT <i>X</i>	1.00	242.50	60.63	181.87	L	Y	
34 REAR LH ROOF TOP OUTER MOULDING (SMALL) <i>re m13</i>	1.00	54.40	13.60	40.80	L	Y	
35 ROOF TOP CENTER OUTER MOULDING (BIG) <i>re</i>	1.00	656.90	164.23	492.67	L	Y	
36 SPARE TYRE BOARD <i>re</i>	1.00	519.00	129.75	389.25	L	Y	
37 SPARE TYRE LOCK <i>X</i>	1.00	20.80	5.20	15.60	L	Y	
38 REAR END PANEL TRIM BOARD <i>?</i>	1.00	105.80	26.45	79.35	L	Y	
39 REAR LH LUGGAGE SIDE TRIM <i>?</i>	1.00	355.90	88.98	266.92	L	Y	
40 REAR RH LUGGAGE SIDE TRIM <i>?</i>	1.00	355.90	88.98	266.92	L	Y	
41 REAR LH LUGGAGE TRAY <i>?</i>	1.00	313.00	78.25	234.75	L	Y	
42 REAR RH LUGGAGE TRAY <i>?</i>	1.00	313.60	78.40	235.20	L	Y	
43 TAILLAMP LOWER LH <i>?</i>	1.00	502.00	125.50	376.50	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
44 TAILLAMP UPPER LH <i>cm</i>	1.00	443.30	110.83	332.47	L	Y	
45 TAILLAMP COVER LH <i>cm</i>	1.00	64.50	16.13	48.37	L	Y	
46 TAILLAMP LOWER RH <i>cm</i>	1.00	502.00	125.50	376.50	L	Y	
47 TAILLAMP UPPER RH <i>cm</i>	1.00	451.80	112.95	338.85	L	Y	
48 TAILLAMP COVER RH <i>cm</i>	1.00	64.50	16.13	48.37	L	Y	
49 FRONT BUMPER <i>de</i>	1.00	516.00	129.00	387.00	L	Y	
50 FRONT LH BUMPER RETAINER <i>X</i>	1.00	82.30	20.58	61.72	L	Y	
51 FRONT RH BUMPER RETAINER <i>X</i>	1.00	80.10	20.03	60.07	L	Y	
52 FRONT BUMPER ENERGY ABSORBER <i>cm</i>	1.00	79.60	19.90	59.70	L	Y	
53 FRONT BUMPER REINFORCEMENT <i>4</i>	1.00	716.60	179.15	537.45	L	Y	
54 FRONT LH BUMPER TOWING COVER <i>X</i>	1.00	29.30	7.33	21.97	L	Y	
55 RADIATOR GRILLE <i>cm</i>	1.00	346.00	86.50	259.50	L	Y	
56 RADIATOR GRILLE EMBLEM <i>re</i>	1.00	90.80	22.70	68.10	L	Y	
57 RADIATOR GRILLE LOWER NO.1 <i>X</i>	1.00	170.10	42.53	127.57	L	Y	
58 FRONT BUMPER LICENCE PLATE MOULDING <i>cm</i>	1.00	103.40	25.85	77.55	L	Y	
59 FRONT LH FOG LAMP <i>X</i>	1.00	951.40	237.85	713.55	L	Y	
60 FRONT BUMPER UNDERTRAY COVER <i>X</i> (SMALL)	1.00	241.90	60.48	181.42	L	Y	
61 FRONT RH BUMPER TOWING COVER <i>X</i>	1.00	29.30	7.33	21.97	L	Y	
62 AIR CLEANER INLET NO. 1 <i>X</i>	1.00	155.60	38.90	116.70	L	Y	
63 AIR CLEANER INLET NO. 2 <i>X</i>	1.00	112.70	28.18	84.52	L	Y	
64 AIR CLEANER INLET NO.3 <i>X</i>	1.00	42.10	10.53	31.57	L	Y	
65 AIR CLEANER BOX ASSY <i>X</i>	1.00	1,147.00	286.75	860.25	L	Y	
66 AIR CLEANER HOSE NO.1 <i>X</i>	1.00	74.00	18.50	55.50	L	Y	
67 HORN LH <i>X</i>	1.00	134.80	33.70	101.10	L	Y	
68 HORN RH <i>X</i>	1.00	134.80	33.70	101.10	L	Y	
69 A/C CONDENSER <i>?</i>	1.00	1,783.20	445.80	1,337.40	L	Y	
70 FRONT BUMPER LOWER ABSORBER <i>X</i>	1.00	132.70	33.18	99.52	L	Y	
71 FRONT LH HEADLAMP <i>?</i>	1.00	2,637.60	659.40	1,978.20	L	Y	
72 FRONT RH HEADLAMP <i>?</i>	1.00	2,637.60	659.40	1,978.20	L	Y	
73 FRONT LH HEADLAMP PANEL <i>?</i>	1.00	78.90	19.73	59.17	L	Y	
74 FRONT RH HEADLAMP PANEL <i>?</i>	1.00	78.90	19.73	59.17	L	Y	
75 RADIATOR SUPPORT PANEL LH <i>?</i>	1.00	245.10	61.28	183.82	L	Y	
76 RADIATOR SUPPORT PANEL RH <i>?</i>	1.00	245.10	61.28	183.82	L	Y	
77 RADIATOR SUPPORT PANEL UPPER <i>?</i>	1.00	377.10	94.28	282.82	L	Y	
78 RADIATOR SUPPORT PANEL LOWER <i>?</i>	1.00	409.90	102.48	307.42	L	Y	
79 BASE BATTERY TRAY <i>?</i>	1.00	167.30	41.83	125.47	L	Y	
80 FRONT LH FENDER LINER <i>X</i>	1.00	202.50	50.63	151.87	L	Y	
81 FRONT LH FENDER EMBLEM <i>re</i>	1.00	54.90	13.73	41.17	L	Y	
82 FRONT RH FENDER LINER <i>X</i>	1.00	206.70	51.68	155.02	L	Y	
83 FRONT RH FENDER EMBLEM <i>re</i>	1.00	54.90	13.73	41.17	L	Y	
84 FRONT BONNET <i>4</i>	1.00	983.10	245.78	737.32	L	Y	
85 FRONT BONNET INSULATOR <i>X</i>	1.00	410.90	102.73	308.17	L	Y	
86 FRONT BONNET LOCK <i>?</i>	1.00	135.00	33.75	101.25	L	Y	
87 FRONT BONNET LOCK CABLE <i>X</i>	1.00	54.90	13.73	41.17	L	Y	
88 FRONT BONNET LOCK SUPPORT BRACE <i>?</i>	1.00	78.30	19.58	58.72	L	Y	
89 FRONT LH BONNET HINGE <i>?</i>	1.00	58.90	14.73	44.17	L	Y	
90 FRONT RH BONNET HINGE <i>?</i>	1.00	58.90	14.73	44.17	L	Y	
91 FRONT RH FOG LAMP <i>X</i>	1.00	951.40	237.85	713.55	L	Y	
92 RADIATOR SUPPORT UPPER COVER <i>?</i>	1.00	235.30	58.83	176.47	L	Y	
93 REAR END PANEL <i>4 - photo</i>	1.00	650.30	162.58	487.72	L	Y	
94 REAR FLOOR PAN <i>?</i>	1.00	0.00	0.00	0.00	L	Y	
95 REAR RH ROOF TOP OUTER MOULDING <i>3 mid</i> (SMALL)	1.00	54.40	13.60	40.80	L	Y	
96 FRONT BUMPER CLIP SET <i>m</i>	1.00	55.00	0.00	55.00	S	Y	80
97 RADIATOR COOLANT <i>?</i>	1.00	100.00	0.00	100.00	S	Y	860?
98 FRONT BUMPER UNDERTRAY COVER CLIP <i>X</i>	1.00	55.00	0.00	55.00	S	Y	X
99 FRONT LICENCE PLATE NUMBER WITH <i>4</i> FRAME	1.00	80.00	0.00	80.00	S	Y	35

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
10 FRONT FENDER INNER SHIELD CLIP SET	1.00	55.00	0.00	55.00	S	Y	X
10 FRONT BONNET INSULATOR CLIP	1.00	50.00	0.00	50.00	S	Y	30
10 BATTERY	1.00	350.00	0.00	350.00	S	Y	?
10 REAR BUMPER CLIP SET	1.00	55.00	0.00	55.00	S	Y	30
10 REAR REVERSE SENSOR SET	2.00	300.00	0.00	300.00	S	Y	200
10 REAR LICENCE PLATE NUMBER WITH FRAME	1.00	80.00	0.00	80.00	S	Y	30 X
10 REAR BUMPER UNDER COVER CLIP SET	1.00	55.00	0.00	55.00	S	Y	30
10 REAR BUMPER PROTECTOR	1.00	120.00	0.00	120.00	S	Y	50
10 TAILLAMP GUIDE CLIP SET	1.00	50.00	0.00	50.00	S	Y	30
10 REAR TAILGATE "6552-1111" STICKER	1.00	100.00	0.00	100.00	S	Y	60
11 REAR TAILGATE "COMFORT DELGRO" STICKER	1.00	100.00	0.00	100.00	S	Y	60
11 REAR TAILGATE "BOOK NOW" STICKER	1.00	100.00	0.00	100.00	S	Y	60
11 REAR TAILGATE OUTER GARNISH CLIP	1.00	50.00	0.00	50.00	S	Y	30
11 REAR WINDSCREEN SEALANT	3.00	150.00	0.00	150.00	S	Y	50
11 REAR WINDSCREEN PRIMER	2.00	100.00	0.00	100.00	S	Y	50
11 REAR END PANEL SEALANT	2.00	120.00	0.00	120.00	S	Y	40
11 REAR TAILGATE SPOILER CLIP SET	1.00	50.00	0.00	50.00	S	Y	30
TOTAL:		33,645.70	,867.94	25,777.76			

TOTAL PARTS & LABOUR : 43,645.70 7,867.94 35,777.76

EXCESS/LOADING:\$\$ 0.00

No. Of Day:

14 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM \$\$

DATE OF SURVEY:

11 / 07 / 23

SURVEYED BY:

Ross

CONTACT NO:

9606068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STAAUTOCENTRE

TEL:

FAX:

Request for MV

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

839G

Vehicle Details

Vehicle No.:

SHA9358J

Vehicle to be Exported:

Yes

Intended Deregistration Date:

11 Jul 2023

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS HYBRID 1.8 CVT

Primary Colour:

Yellow

Manufacturing Year:

2017

Engine No.:

2ZRS056101

Chassis No.:

JTDKB3FU903561309

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$29,007.00

Original Registration Date:

17 Aug 2017

First Registration Date:

17 Aug 2017

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

16 Aug 2025

PARF Rebate Amount:

\$3,500.00

Intended COE Rebate Details

COE Expiry Date:

16 Aug 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$36,320.00

COE Rebate Amount:

\$9,519.00

Total Rebate Amount:

\$13,019.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Jul 2023

OK