

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 23.30781 Date: 13th July 2023

Our Ref: CS3/ASM22008366/Dnp3e2-1

## M/s HSBC Life (Singapore) Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FW 7432Z

INSURED VEHICLE: SH 7480J ACCIDENT DATE: 27/08/2022

We thank you for your instruction on 12/07/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FW 7432Z from M/s Aeon Auto Consultants LLP.
- b) Singapore Accident Statement of Vehicles FW 7432Z and SH 7480J.
- c) Police Report of Vehicles FW 7432Z.
- d) Final Repair Bill of FW 7432Z from M/s Motocraft Pte Ltd.

Pre-Repair Inspection Date: 29/08/2022 at M/s Motocraft Pte Ltd, 7 Soon Lee Street #01-18, Singapore 627608.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FW 7432Z

Make & Model : Honda Wave125S

Year of Registration : 2003

Chassis Number : NF125MD0058409

Engine Capacity : 125 cc

- 2. We recommend that the repairs of the entire damage require about <u>3 (Three)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.