

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST:201119451E RCB NO:201119451E

M/S : **Lonpac Insurance BHD**
300 Beach Road #17-04/07
The Concourse
Singapore 199555

TEL: FAX:
 ATTN: Motor Claim Department
 Your Ref No : 23/LP/OD-413 (07)
 Claim Type : OD CLAIM
 Accident Date : 08/07/2023

Claim No :
 No :
 Date : 12/07/2023
 Policy No : Z22VP05032428
 Veh Reg No : SFJ3139R
 Make / Model : Hyundai Elantra
 Chassis No :
 Engine No :
 Reg. No :

not follow
 all
 excess nil
 12/7/23
 Take photo before
 away.
 5 days.
 P/P#7900.60

ESTIMATE FOR VEHICLE NO: SFJ3139R

Discription	Quantity	List Price	Amount
Cost Price			SS
1 FRT BONNET (NO STOCK)	1 PC	Bull \$850.00	==
2 FRT BONNET HINGE (NO STOCK)	2PCS	Bull \$110.00	==
3 FRT BONNET LOCK	1 PC	Tur \$85.00	==
4 FRT GRILLE	1 PC	Bull \$295.00	==
5 FRT GRILLE CLIP	4PCS	Rec \$8.00	==
6 FRT BUMPER	1 PC	Tur \$350.00	==
7 FRT BUMPER RETAINER	2PCS	Bull \$40.00	==
8 FRT BUMPER CLIP	10PCS	Rec \$20.00	==
9 FRT BUMPER INNER SPONGE (NO STOCK)	1 PC	Tur \$120.00	==
10 FRT BUMPER REINFORCEMENT (NO STOCK)	1 PC	Bull \$320.00	==
11 HEADLAMP (NO STOCK)	2PCS	Tur \$1,100.00	1 PC 550.
12 HEADLAMP SUPPORT PANEL (NO STOCK)	1 PC	Cue \$450.00	==
13 HEADLAMP SUPPORT TOP GARNISH	1 PC	Bull \$60.00	==
14 SUPPORT TOP GARNISH CLIP	8PCS	Rec \$16.00	==
15 AIRCON CONDENSEP	1 PC	Tur \$495.00	==
16 RADIATOR	1 PC	Bull \$450.00	==
17 RADIATOR FAN ASSY	1 PC	Rec \$380.00	X
18 AIR DUCT	1 PC	Tur \$75.00	==
19 AIR HOSE	1 PC	Rec \$75.00	X
20 AIR CLEANER BOX (NO STOCK)	1 PC	Rec \$195.00	X
21 HEADLAMP LOWER BRACKET	2PCS	N/S.cue \$50.00	1 PC 25.
22 FRT BUMPER SIDE BRACKET	2PCS	N/S.cue \$40.00	1 PC 20.
23 RADIATOR TOP HOSE	1 PC	Rec \$30.00	X
24 THROTTLE BODY (NO STOCK)	1 PC	Cue \$450.00	==
25 AIR FLOW SENSOR	1 PC	Rec \$110.00	X
26 FRT LH FENDER INNER COWLING (NO STOCK)	1 PC	Rec \$280.00	==
27 INNER COWLING CLIP	10PCS	Rec \$20.00	X
28 NUMBER PLATE GARNISH	1 PC	Bull \$25.00	==
29 FRT BUMPER TOP RUBBER SEAL (NO STOCK)	1 PC	Tur \$130.00	50.
		\$6,629.00	
		\$994.35	\$7,623.35

Add 15%

4864

Special Net

1	NUMBER PLATE	1 PC	Bull \$35.00	✓
2	RADIATOR COOLANT	1 PC	Rec \$25.00	20
			\$60.00	

Labour

1	WIRE CHECKING	\$30.00	20
2	REMOVE & REFIX AIRCON AND GAS	\$100.00	✓
3	REMOVE & REFIX THROTTLE BODY + menibold	\$150.00	✓
4	LABOUR CHARGE	\$700.00	600
5	SPRAY PAINTING	\$700.00	600
		\$1,680.00	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

For SME MOTOR PTE LTD

Signature: _____
 Date: _____

Amount Before Excess	\$9,363.35
Less Excess	\$0.00
Amount Before GST	\$9,363.35
Add GST @8%	\$749.06
Total Amount Payable	\$10,112.41

P-5504
 +15
 P.6375.60
 S.N-55
 2-1470
 7900.6