



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC23007065/Kvy3m4 Date: 27/07/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 5171L	Veh. Inspected	SBS 8399Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	22/2/23/VC05/027681	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	13/07/2023	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA (A)	c.c	8867	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	YS2K4X20001861947	Colour	MULTI COLOUR	
Odometer	1049825 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	9 mm	
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	9 mm	
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/07/2023	Inspection Date	13/07/2023	
Survey held at	15 ANG MO KIO ST 63 SINGAPORE 569117			
Repairer	SBS TRANSIT LTD (HQ)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	