



1

of 2 ?



100%



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD		Ref: CS/INC23007069/Tqy3		
75 BRAS BASAH ROAD		Date: 13/07/2023		
INCOME CENTRESINGAPORE 189557				
ATTN: EILEEN LEE		Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 4170X	Veh. Inspected	SJT 786S	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1231239-002	Excess (\$)	0.00	
Assign From		Assign Date	12/07/2023	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/07/2023	Inspection Date	12/07/2023	
Survey held at	AP AUTOMOTIVE SERVICES PTE LTD 9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				