

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHAN KIM MUN
 36 SERENADE WALK
 575785

Estimate No: MC1903625
 Date: 07 Jul 2023
 Policy No: P10255300R03
 Veh Reg No: SLH3379D
 Make/Model: MITSUBISHI AXS

ATTN:
 Your Ref No: -
 Claim Type: Third Party
 Accident Date: 05/07/2023
 TP Veh Reg No: SLC7310B

Not Authorised
Repairing B4 pain
2 days

Estimate Repair Cost to Vehicle No :SLH3379D

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
SPARE PARTS			
1 TAILGATE ASX LOGO	1 PC	nn 50.00 X	
2 TAILGATE MIVEC LOGO	1 PC	nn 95.00 X	
3 TAILGATE CC LOGO -check price	1 PC	nn 0.00 X	
4 REAR BUMPER	1 PC	CM 730.00 ✓	
5 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	nn 48.00 X	
6 REAR BUMPER CLIPS	1 PC	nn 5.00 ✓	
7 REAR BUMPER CENTER COVER	1 PC	nn 40.00 X	
8 REAR BUMPER TOW COVER RH	1 PC	nn 20.00 ✓	
9 REAR BUMPER REINFORCEMENT	1 PC	210.00 ?	
10 REAR BUMPER REINFORCEMENT BRACKET LH & RH	2 PC	44.00 ?	
11 END PANEL	1 PC	nn 285.00 X	
12 REAR EXHAUST PIPE	1 PC	861.00 ?	
13 REAR EXHAUST PIPE MOUNTING	3 PC	84.00 ?	
		2,472.00	
		Less 10%	
		247.20	2,224.80
Special Nett			
14 REVERSE SENSOR	1 PC	CM 200.00 ✓	
		200.00	200.00
LABOUR			
15 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 15/	
16 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	60.00 50/	
17 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	nn 60.00 X	
18 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00 ?	
19 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR TAILGATE & INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00 200/	
20 TO SPRAY TAILGATE, REAR BUMPER, END PANEL	1 PC	600.00 220/	
		1,440.00	1,440.00

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: