

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS4/CTI23007097/TNP3E2**Date:** 03/08/2023**REFERENCE**

Insured/Claimant:	CHUA KOK WEI	Policy No:	DMPCSNA00134292215
Date of Loss:	09/07/2023	Nature of Claim:	OD
		Claim No:	SNM23D204795/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDK8922G		
Make & Model:	TOYOTA PREVIA, 2.4 8-SEATER (A)	Engine No:	2AZ2231698
Reg. Date:	06/06/2006 (Man. Year: 2006)	Chassis No:	JTEGD52MX07029721
Colour:	Silver	Odometer:	0 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	170.00	170.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	170.00	170.00	0.00	0.00
+ GST 8.00/0.00% (S\$)	13.60	0.00	13.60	100.00
Nett Amount (S\$)	183.60	170.00	13.60	7.41

INSPECTION

Date of Assignment: 13/07/2023

Date Inspected: 13/07/2023 Inspected At:

Cheng Hoe Motor Pte Ltd
38 Woodlands Industrial Park E1 #05-04/05
Singapore 757700

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$50,000.00
OMV :	\$36,202.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$46,048.00
COE Rebate (2) :	\$13,306.00
Total Rebate (1) + (2) = :	\$13,306.00

The total amount incurred will be Market Value \$50,000.00 minus Total Rebate \$13,306.00 = \$36,694.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2023)
Parts:	M1-MPV	TOYOTA PREVIA 2.4 8-SEATER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDK8922G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Towing (from scene to Owners own workshop) - by owner	New	120.00	120.00
2	Towing (from own workshop to Cheng Hoe,Woodlands)	New	50.00	50.00
Gross Labour Cost (\$\$)			170.00	170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >