

ASS. REP. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insured Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claim's No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBKS136C Yr Regn: 2020, Augst.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Topla Dyna C.C. 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 210748 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35Y10K215233

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 155R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

*Survey held at SV

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I.

13/07/23

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>PD Ergo.</u>
	<u>COE Expiry :</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV : 98K</u>
	<u>PV : 17K.</u>
	<u>Nett : 81K.</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation:

3 + RS. \$ _____

Photos

Others

Report Forward:

Insurance / P.P. / C.



SV AUTOWORKS PTE LTD
8 Kaki Bukit Avenue 4
#02-24 Premier@ Kaki Bukit
Singapore 415875

Attention To:

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard #04-01
Suntec Tower Three
Singapore 038988

Vehicle Details

Make & Model : Toyota Dyna
Chassis No : JTFAT35Y10K215233
Registration No : GBK 5136 C

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	Description	Qty	Amount (\$S)
1	Front door <i>Disturbed</i>		\$ 1,794.22 ✓
2	Front door top hinge <i>3 Bent</i>		\$ 78.50 ✓
3	Front door bottom hinge		\$ 78.50 ✓
4	Front door checker <i>Bent</i>		\$ 131.75 ✓
5	Front door weatherstrip <i>?</i>		\$ 149.60 ?
6	Front door glass <i>Shattered</i>		\$ 448.55 ✓
7	Front door glass outer moulding <i>Disturbed</i>		\$ 205.70 ✓
8	Front door glass inner moulding <i>?</i>		\$ 122.65 ?
9	Front door glass regulator gear <i>?</i>		\$ 295.65 ?
10	Front door glass regulator motor <i>?</i>		\$ 509.35 ?
11	Front door glass channel <i>Bent</i>		\$ 245.30 ✓
12	Front door outer handle <i>new</i>		\$ 163.50 ✓
13	Front door inner trim <i>Disturbed</i>		\$ 897.50 ✓
14	Front door lock <i>Jammed</i>		\$ 375.85 ✓
15	Front door lock latch <i>?</i>		\$ 42.60 ✓
16	Front door inner handle <i>?</i>		\$ 86.95 ✓
17	Front door power motor control <i>new</i>		\$ 256.50 ✓
18	Front door inner pillar <i>3 Bent</i>		\$ 381.60 ✓
19	Front door outer pillar		\$ 398.70 ✓
20	Front door lower rubber <i>?</i>		\$ 83.50 ✓
21	Front door specker <i>?</i>		\$ 288.70 ✓
22	Front door frame rubber <i>?</i>		\$ 190.05 ✓
23	Front step garnish <i>Disturbed</i>		\$ 325.50 ✓
24	Front side mirror <i>new</i>		\$ 272.20 ✓
25	Front arch panel <i>Disturbed</i>		\$ 569.20 ✓
26	Front arch panel garnish <i>Disturbed</i>		\$ 122.80 ✓
27	Front seat belt <i>new</i>		\$ 497.12 ✓
28	Dash board <i>?</i>		\$ 973.40 ?
29	Dash board side garnish		\$ 164.70 ?
30	Front windscreen glass moulding <i>new</i>		\$ 369.70 ✓
31	Front wiper panel <i>Disturbed</i>		\$ 594.60 ✓
32	Front panel <i>Disturbed</i>		\$ 1,313.74 ✓

33	Front panel emblem DYNA <i>me</i>		\$	69.74	✓
34	Head lamp <i>could</i>		\$	997.30	✓
35	Head lamp lower rubber <i>at</i>		\$	47.20	✓
36	Front corner panel <i>needed</i>		\$	427.50	✓
37	Brake master pump ?		\$	904.58	?
38	Brake booster pump ?		\$	1,935.80	?
39	Brake fluid container ?		\$	225.60	?
40	Brake booster pump bracket ?		\$	134.50	?
41	Front bumper <i>needed</i>		\$	477.60	✓
42	Front bumper bracket <i>best</i>		\$	212.70	✓
43	Front bumper fog lamp cover <i>needed</i>		\$	47.90	✓
44	Front grille <i>needed</i>		\$	479.80	✓
45	Front grille emblem LOGO <i>me</i>		\$	78.20	✓
46	Rear cabin pillar <i>legs</i>		\$	978.90	+
47	Rear cabin pillar inner trim <i>pen</i>		\$	379.20	+

TOTAL LIST \$ 19,824.70
 25% 4956.18
 \$ 14,868.53

S/N	Special Nett	Qty	Amount (\$\$)	
1	Front door inner trim clips <i>me</i>		\$ 50.00	30
2	Front wiper panel clips <i>me</i>		\$ 50.00	30
3	Front grille clips <i>me</i>		\$ 50.00	20
4	Rear cabin pillar inner trim clips <i>new</i>		\$ 50.00	+
5	Front windscreen pillar clips <i>me</i>		\$ 50.00	+
6	Brake fluid oil <i>me</i>		\$ 50.00	+
7	Head lamp lower rubber <i>new</i>		\$ 50.00	+

TOTAL SPECIAL NETT \$ 350.00

S/N	Labour	Qty	Amount (\$\$)	
1	Labour charge		\$ 1,500.00	1400
2	Spray paint charge		\$ 1,500.00	1400
3	Antirust		\$ 150.00	80
4	Rewire		\$ 100.00	30
5	R&R dash board		\$ 300.00	?
6	R&R brake master pump assy		\$ 300.00	?
7	R&R front windscreen glass		\$ 150.00	120
8	Transfer front door attachment		\$ 150.00	60
9	R&R rear inner trim for hot work repair.		\$ 300.00	60
10	Conduct a water leakage test		\$ 100.00	+
11	Redo the sealant on the gap to facilitate the repair		\$ 100.00	60
12	Refocus the headlamp beam		\$ 100.00	+

TOTAL LABOUR \$ 4,750.00

TOTAL REPAIR COST \$ 19,968.53

Admin *h/s*
 13/07/23
 be authorized

Excess: To be advised.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	137E
Vehicle Details	
Vehicle No.:	GBK5136C
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	1KDB039060
Chassis No.:	JTFAT35Y10K215233
Maximum Power Output:	-
Open Market Value:	\$29,349.00
Original Registration Date:	14 Aug 2020
First Registration Date:	14 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$1,468.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Aug 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$23,888.00
COE Rebate Amount:	\$16,927.00
Total Rebate Amount:	\$16,927.00

The information contained herein is correct as at 12 Jul 2023

OK

**sgcarmart**
[New Cars](#) [Used Cars](#) [Car Loan](#) [Rental Cars](#) [Sell Cars](#) [Directory](#) [Products](#) [Insurance](#) [Articles](#) [Forum](#) [Resources](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Opel Grandland X 1.2a Turbo Innovation Premium



Fully Agent Maintained. Under 5
Years Agent Warranty And
Servicing. Low Depre. ja
Direct Owner StarAd

Sort by 20 results/page

5 vehicles



toyota dyna

Any Category

Advanced Search



Search

Search Selection

toyota dyna

Toyota Dyna 150 3.0M**Fuel Type:** Diesel

Authentic Low Mileage Lorry. 1 Owner Only. Original Paintwork! Excellent Condition! 100% Loan Available! High Trade In! Call Us For Appointment To View!

ABWIN (1994) Pte Ltd

Posted: 12-Jul-2023

**Toyota Dyna 150 3.0M****Fuel Type:** Diesel

One Owner Newly Released Toyota Dyna. New Paintwork. Tip Top Conditions. Most Reliable Model 10ft Lorry In The Market. Fitted With Canopy. Most Ideal For Construction Usage. In House Or Bank Loan Can Be Arranged. Trade In Most Welcome.

Posted: 03-Jul-2023

**Toyota Dyna 150 3.0M****Fuel Type:** Diesel

Low Mileage At 53K Km Only. 1 Owner. Excellent Condition. Doorstep Viewing Can Be Arranged. 100% Loan! High Trade In!. Call Us Now.

ABWIN (1994) Pte Ltd

Posted: 22-Jun-2023

**Toyota Dyna 150 3.0M****Fuel Type:** Diesel

6,000km mileage only! Super rare unit! 1 owner. Fully serviced by agent workshop. Bonus high box with 2 sliding door worth over \$3000 installed. Condition is needless to say, really equivalent to brand new. Come and see.

Posted: 27-Jun-2023

**Edwin Garage - Specialty Workshops**

Edwin Garage Present to you the strongest team in car aircon, Japanese/ Korean car make and continental cars engine specialist.

More info about this shop

**Toyota Dyna 150 3.0M****Fuel Type:** Diesel

Under Utilised 10ft Lorry By Previous Owner. Low Mileage Clocked. 1 Owner. Very Good Condition. Best Selling Model & Well Known For Its Reliability. Flexible Loan Packages & Attractive Interest Rates Available. Come And View.

Posted: 28-Jun-2023



Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Toyota	Dyna	\$90,800	\$13,770 /yr	17-Feb-2020	2,982 cc	59,361 km	Truck	Available
Toyota	Dyna	\$94,800	\$14,220 /yr	16-Mar-2020	2,982 cc	86,741 km	Truck	Available
Toyota	Dyna	\$96,800	\$14,130 /yr	22-May-2020	2,982 cc	53,818 km	Truck	Available
Toyota	Dyna	\$98,800	\$14,360 /yr	02-Jun-2020	2,982 cc	6,000 km	Truck	Available
Toyota	Dyna	\$98,800	\$13,800 /yr	11-Sep-2020	2,982 cc	43,000 km	Truck	Available

20 results/page

For old advertisements, view **Expired ads**

Compare, 21