

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Melvin Ye Yongkang

Date: 17 Jul 2023

**Preliminary Advice**

|                    |  |                         |              |
|--------------------|--|-------------------------|--------------|
| Insured Vehicle No | : EM2263S  | Accident Date           | : 12/07/2023 |
| TP Vehicle No      | : SKR4623B   | Assignment Date         | : 14/07/2023 |
| Make               | : VOLVO S60  | Est. Duration of Repair | : 6          |
| Date of Inspection | : 14/07/2023   |                         |              |
| Inspection At      | : CARWORKZ SG PTE LTD (HQ)<br>BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C, #01-08<br>SINGAPORE 575645 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 24,068.37 |
| Revised Amount              | :S\$ | 11,914.72 |
| Check Items (Estimated)     | :S\$ | 2,200.15  |
| Total                       | :S\$ | 14,114.87 |

Lump Sum Repair :S\$

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 36,000.00 |
| COE / PARF Rebate  | :S\$ | 19,699.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 16,301.00 |

**Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( x ) Lump Sum repair
  
- ( x ) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.