



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

19/7/2023

Survey Details:

Date of loss	11-Jul-23
Date of appointment	13-Jul-23
Date of survey	18-Jul-23
Location of survey	SIN HENG LONG MOTOR WORK

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	SGG 9755B
Make and Model	MAZDA 3 4-DOOR SEDAN 1.5L SP.6EAT
Date of registration	26/5/2016
Excess	-
Market Value	\$ 40,000.00
Part Rebate	\$ 20,218.00
Nett Loss	\$ 19,782.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	2
----------------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$1,500.00 - \$2,500.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	