



Your Ref: 23.30470

Date: 19th July 2023

Our Ref: CS3/ASM22003561/Dnp3e2-1

M/s HSBC Life (Singapore) Pte Ltd

C/o Seah Ong & Partners LLP
36 Robinson Road #12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBR 6863T
INSURED VEHICLE: SH 9740X
ACCIDENT DATE: 14/07/2021**

We thank you for your instruction on 14/07/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBR 6863T from M/s Ajax Inspection Services Pte Ltd
- b) Singapore Accident Statement of Vehicles FBR 6863T and SH 9740X.
- c) Police Report of Vehicles FBR 6863T.
- d) Final Repair Bill of FBR 6863T from M/s Hotwheels SG Pte Ltd.
- e) Colour damaged vehicle photographs of FBR 6863T.

Pre-Repair Inspection Date: 19/04/2022 at M/s Hotwheelz, 23 Kaki Bukit Avenue 4 #01-11 Synergy @ Kaki Bukit, Singapore 417801.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBR 6863T
Make & Model : Yamaha R15 ABS Manual
Year of Registration : 2020
Chassis Number : ME1RG6713L0024987
Engine Capacity : 155 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.