



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22009523/Dnp3m4-1 Date: 20/07/2023 Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBL 1541L	Veh. Inspected	SMR 5014D	
Policy No.	DMCVSNA00117402101	Coverage (\$)	0.00	
Claim No.	SNM22D206873/C02	Excess (\$)	0.00	
Assign From	LYNN KHONG	Assign Date	14/07/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VOXY HYBRID 1.8X	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZWR800279650	Colour	SILVER	
Odometer	71545 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	KAPSEN	6 mm	
L/H Front Tyre	195/65 R15	KAPSEN	6 mm	
R/H Rear Tyre	195/65 R15	KAPSEN	6 mm	
L/H Rear Tyre	195/65 R15	KAPSEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/09/2022	Inspection Date	27/09/2022	
Survey held at	365 AUTOMOTIVE PTE LTD 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	