

Name & Address:

Motor Claims Department

ALLIANZ INSURANCE (S) PTE LTD

79 ROBINSON ROAD #09-01

SINGAPORE 068897

Vehicle No:

SJG28R

Brand & Model:

720S COUPE

Chassis/VIN No:

SBM14DCD8JW000252

Date:

19-Jul-23

Franchise:

MCLAREN

Contact Person (Eurokars):

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

YEAR MODEL:

2017

WIP#:

Contact No (Eurokars):

6331 0680
PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER WITH CAMERA <i>act /</i>	14AC708CP	1		-	\$ 4,037.50
2	REAR BUMPER LOWER CENTER <i>cm /</i>	14AA973CP	1		-	\$ 6,124.10
3	CLIP STEM <i>m /</i>	00RB176	6		-	\$ 399.60
4	DECAL REAR BUMPER LH <i>m /</i>	14AB264CP	1		-	\$ 19.40
5	DECAL REAR BUMPER RH <i>m /</i>	14AB265CP	1		-	\$ 19.40
6	CLIP U NUT <i>m /</i>	00RB194	25		-	\$ 222.00
7	REAR BUMPER CENTER LOWER BRACKET ?	14A3064CP	1		-	\$ 172.70
8	BLACK DECAL BODY SIDE LOWER ?	11A4758CP	2		-	\$ 178.00
9	REAR CAMERA BRACKET <i>m /</i>	14AB623CP	1		-	\$ 322.30
10	REAR CAMERA COVER ?	14AB858CP	1		-	\$ 70.00
11	REAR BUMPER EXTENSION UPPER ?	14AC374CP	1		-	\$ 2,735.20
12	SCREW FOR BUMPER <i>m /</i>	00RA468	18		-	\$ 568.95
13	REAR BUMPER REINFORCEMENT ?	14A1962CP	1		-	\$ 3,650.90
14	REAR BUMPER GRILLE RH X	14A3606CP	1		-	\$ 1,596.20
15	REAR BUMPER GRILLE LH ?	14A3605CP	1		-	\$ 1,596.20
16	HEATSHIELD FOR CAMERA ?	14AB553CP	1		-	\$ 263.25
17	REAR BUMPER GRILLE CENTER X	14AB132CP	1		-	\$ 2,399.10
18	LOGO MCLAREN X	14AC666CP	1		-	\$ 873.75
19	REAR BUMPER DIFFUSER ?	14A2325CP	1		-	\$ 8,539.90
20	REAR BUMPER DIFFUSER BRACKET OUTER LH ?	14A0340CP	1		-	\$ 217.45
21	REAR BUMPER DIFFUSER BRACKET CENTER LH ?	14AC540CP	1		-	\$ 145.55
22	REAR BUMPER DIFFUSER BRACKET CENTER RH ?	14AC541CP	1		-	\$ 145.55
23	REAR BUMPER DIFFUSER BRACKET OUTER RH ?	14A0341CP	1		-	\$ 217.45
24	SCREW FOR BRACKET ?	00RA263	10		-	\$ 892.50
25	REFLECTOR LH <i>MIS /</i>	13A3750CP	1		-	\$ 167.95
26						\$

Sub-Total (Parts Price) \$ 35,074.90

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE

1	TO REMOVE /REPLACE REAR BUMPER, LOWER BUMPER, DIFFUSER & ALL ACCIDENT DAMAGED BODY PARTS. TO REALIGN THE REAR UPPER SPOILER & REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. @ 2080	4160	\$ 6,240.00
2	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER & REAR DIFFUSER @ 2500	2500	\$ 8,750.00
3	TO SUPPLY REAR LICENCE PLATE WITH CASING ✓	nett	\$ 150.00
4	TO TRANSFER THE REVERSE CAMERA.	nett	\$ 500 1,000.00
5	TO SUPPLY/ INSTALL THE BODY WRAP STICKER (PRICE TO BE ADVISE)	nett	\$ 600
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	nett	\$ 1,000.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 1,500.00
8	SUNDRIES.	nett	\$ 50 100.00

Survey Date & Time: 20/07/23 @ 1440	Repair Days: 5 days	Excess:
--	------------------------	---------

Surveyor Remarks:

Rasul
Resy 64 paint

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 18,740.00

	REVISED	PRICE
Parts Price	\$ -	\$ 35,074.90
Labour Price	\$ -	\$ 18,740.00
Total (Initial Estimate)	\$ -	\$ 53,814.90
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 53,814.90
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 53,814.90
GST 8%	\$ -	\$ 4,305.19
GRAND TOTAL	\$ -	\$ 58,120.09

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: