

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR23007232/Kny3
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	18/07/2023
				Code:	SMR
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SG 6028U	Veh. Inspected	i	SJS 3324C
	Policy No.		Coverage (\$)		0.00
	Claim No.	BUS/07/23/5025	Excess (\$)		0.00
	Assign From	HUA YEN	Assign Date		17/07/2023
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	Steering			
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	14/07/2023	Inspection Dat	e	18/07/2023
	Survey held at	AUTHORIZE WORKSHOP PTE LTD			
		160 SIN MING DRIVE #03-19, SIN MING AUTOCITY, SINGAPORE 575722			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				