



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Bldg Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	Ms Thanaletch D/O Kathirveil Mrs Thanaletchimi Gan 469 Choa Chu Kang Avenue 3 #02-109 Singapore 680469 Mobile: 97901321
	Document No. 0	
	Document Date 28/07/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ S3	01/12/2016	SLJ2249S	0	23202	72/DS/SLJ2249S
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR053REH104550412	1ZRX571487	60	Thomas Pang W T	18/07/2023	8.00	27/07/2023	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI TP INS:FIRST CAPITAL INSURANCE TP VEH:SMB5030R DATE OF ACC:15.07.2023 TOW IN:15.07.2023 BY:LKK-RASUL @ 18.07.2023 09 WORKING DAYS				50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
3	B	BP-LAB2 CHECK WIRING SYSTEM	BP58			134.64
4	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR	BP58			198.00
5	B	BP-LAB2 REMOVE AND TRANSFER BOOTLID COMPONENTS ONTO NEW BOOTLID. R/I REAR REVERSE CAMERA TO FAC REPAIR	BP58			594.00
6	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	BP58			396.00
7	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	BP63			198.00
8	B	BP-LAB2 REPLACE ACC DAMAGED PARTS	BP58			3960.00
9	B	BP-RES2 RESPRAY ACC AFFECTED AREAS	*			3280.00
10	B	BP-LAB2 TOWING CHARGES	BP58			120.00
11	1	SPC507-47009 00 BACK SENSOR (PRIMER)	1.00	167.50		167.50
12	2	S52159-0Z904 COVER, RR BUMPER	1.00	754.10		754.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1 Document No. 0 Document Date 28/07/2023	Ms Thanaletch D/O Kathirveil Mrs Thanaletchimi Gan 469 Choa Chu Kang Avenue 3 #02-109 Singapore 680469 Mobile: 97901321

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ S3	01/12/2016	SLJ2249S	0	23202	72/DS/SLJ2249S

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH104550412	1ZR571487	60	Thomas Pang W T	18/07/2023 8.00	27/07/2023 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	3	S52161-0K040 PIECE, RR BUMPER	10.00	5.30		53.00
14	4	S58307-02380 PANEL SUB-ASSY, BODY	1.00	912.00		912.00
15	5	S64401-02B71 PANEL SUB-ASSY, LUGG	1.00	1071.10		1071.10
16	6	S64461-02220 WEATHERSTRIP, LUGGAG	1.00	224.80		224.80
17	7	T90467-08186 C0 CLIP	2.00	3.60		7.20
18	8	S75431-02090 EMBLEM, LUGGAGE COMP	1.00	79.30		79.30
19	9	S75442-02330 PLATE, LUGGAGE COMPT	1.00	52.50		52.50
20	0	S75442-02340 PLATE, LUGGAGE COMPT	1.00	58.50		58.50
21	1	S76801-02E30 GARNISH SUB-ASSY, BA	1.00	312.20		312.20
22	2	S81550-02780 LAMP ASSY, RR COMBIN	1.00	515.10		515.10
23	3	S81560-02780 LAMP ASSY, RR COMBIN	1.00	515.10		515.10
24	4	T81496-60010 GUIDE, RR	2.00	4.60		9.20
25	5	S81590-02551 LAMP ASSY, RR, LH	1.00	534.90		534.90
26	6	S52023-02190 REINFORCEMENT SUB-AS	1.00	542.60		542.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			14,939.74
	Please acknowledge receipt of vehicle	Parts 5,809.10 Labour 9,130.64 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	GST 8.00% 1,195.18
			Less 0.00
			Amount Due 16,134.92

Company Copy