

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0676/2023/EQ
DATE : 19-Jul-23
WIP : 29604

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/7/2023
YOUR INSURED VEH NO : SDM 8993 R

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR TAN GIM HOE
ADDRESS : BLK 5 TOH YI DRIVE
#13-237
SINGAPORE 590005
TELEPHONE : HP +65 97878263
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700061762-05
VEHICLE NO : **SFX 17 E**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 11/10/2017
ENGINE NO : CVK 046994
CHASSIS NO : WAUZZZF53JA034298
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Jul-23
PLACE OF ACCIDENT : BLK 1A HDB TOH YI MSCP AT LEVEL 2B

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFX 17 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	257
3	TO REMOVE AND TRANSFER RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00	+
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.	\$ 3,000.00	1100
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	+
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 7,032.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFX 17 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Del</i>	1	\$ 2,642.00	✓
2	FRONT BUMPER FIXING PARTS <i>Not u</i>	1	\$ 452.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH <i>Not u</i>	2	\$ 84.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not u</i>	1	\$ 269.00	+
5	FRONT BUMPER AIR GUIDE - RH <i>Not u</i>	1	\$ 67.00	+
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Not u</i>	1	\$ 562.00	+
7	FRONT BUMPER GUIDE SECTION - RH ?	1	\$ 43.00	?
8	FRONT BUMPER FOAM FILLER PIECE <i>Not u</i>	1	\$ 147.00	+
9	FRONT BUMPER REINFORCEMENT BEAM <i>Not u</i>	1	\$ 953.00	+
10	FRONT BUMPER TOP COVER <i>2</i>	1	\$ 151.00	+
11	CAUTION SIGN STICKER	1	\$ 17.00	+
12	AIR CONDITIONER STICKER <i>Not u</i>	1	\$ 9.00	+
13	FRONT BUMPER BRACKET <i>2</i>	1	\$ 163.00	+
14	FRONT BUMPER SUPPORT - LH / RH <i>2</i>	2	\$ 68.00	X
15	FRONT PARKING AID SENSOR - OUTER	1	\$ 272.00	X
16	FRONT PARKING AID SEAL RING	4	\$ 11.00	X
17	FRONT BUMPER WIRING SET <i>Not u</i>	1	\$ 573.00	X
18	HORN LOW TONE - RH	1	\$ 149.00	X
19	HORN BRACKET - RH	1	\$ 35.00	X
20	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,258.00	✓
SUB TOTAL SPARE PARTS			\$ 7,925.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFX 17 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 59.00	+
22	FRONT FENDER CLOSING ELEMENT - RH <i>new</i>	1	\$ 88.00	+
23	FRONT FENDER BRACKET - RH FRONT ?	1	\$ 44.00	?
24	FRONT FENDER RIVET ?	6	\$ 24.00	?
25	FRONT FENDER DEFORMATION ELEMENT BACKET - RH <i>new</i>	1	\$ 59.00	+
26	FRONT FENDER BRACKET - RH CENTER ?	1	\$ 42.00	?
27	FRONT FENDER BRACE - RH ?	1	\$ 140.00	?
28	FRONT FENDER CHROME TRIM - RH <i>new</i>	1	\$ 181.00	✓
29	FRONT DOOR CHROME TRIM - RH <i>new</i>	1	\$ 181.00	+
30	FRONT WHEEL HOUSING LINER - RH ?	1	\$ 322.00	?
31	FRONT WHEEL SPOILER <i>new</i>	1	\$ 87.00	+
32	FRONT WHEEL SPOILER END PLATE - RH	1	\$ 43.00	+
33	FRONT WHEEL SPOILER STONE CHIP GUARD - RH <i>2nd</i>	1	\$ 60.00	+
34	FRONT WHEEL SPOILER TRIM BRACKET <i>2nd</i>	1	\$ 29.00	+
35	FRONT FENDER LEDGE COVER - LONG <i>2nd</i>	1	\$ 42.00	+
36	FRONT FENDER LEDGE COVER - RH SHORT <i>new</i>	1	\$ 19.00	+
37	HEADLIGHT - RH <i>new</i>	1	\$ 8,909.00	✓
38	LIFT CYLINDER - RH <i>2nd</i>	1	\$ 230.00	+
39	LIFT CYLINDER BRACKET - RH <i>2nd</i>	1	\$ 17.00	+
40	LIFT CYLINDER CORRUGATED PIPE <i>new</i>	1	\$ 104.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,680.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFX 17 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00	+
42	RADIATOR AIR GUIDE - RH	1	\$ 38.00	+
43	RADIATOR AIR GUIDE - LH / RH	2	\$ 50.00	+
44	FRONT ALUMINIUM RIM - RH	1	\$ 2,000.00	+
45	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	+
46	SUNDRIES		\$ 800.00	?
TOTAL SPARE PARTS		:	\$ 21,519.00	
TOTAL LABOUR CHARGES		:	\$ 7,032.00	
GRAND TOTAL		:	\$ 28,551.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

1. This is a copy of the original document.
 2. It is a copy of the original document.
 3. It is a copy of the original document.
 4. It is a copy of the original document.
 5. It is a copy of the original document.
 6. It is a copy of the original document.
 7. It is a copy of the original document.
 8. It is a copy of the original document.
 9. It is a copy of the original document.
 10. It is a copy of the original document.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Ling

SURVEYED DATE

:

21/07/23

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 07 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT