

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Endoration Internation	aala Daa Eynarta Er	. Automa	hile 000	// DO000004
	LONDAC INCLIDA	Affiliated to Federation Internation  LONPAC INSURANCE BHD			CS3/LPC230	/LPC2300601
				Ref:		•
	300 BEACH ROAD #17-04/07 THE CC	NCOURSESINGAPORE 199555		Date:	<del>14/06/2023</del>	18/07/2023
				Code:	LPC2	
	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GR 663J	Veh. Inspected	k	SMC 5849R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From	CHARMAINE KONG	Assign Date		13/06/2023	18/07/2023
2.		Vehicle Partic	culars & Condit	ion		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
•		Condition	ons of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
١.		Description	on of Damages			
5.	T		I Information			
	Accident Date	12/06/2023	Inspection Dat	te	14/06/2023	
	Survey held at	WAH YU AUTOMOTIVE BODY V	WORK			
		176 SIN MING DRIVE #05-09 SINGAPORE 575721				
Ба.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.					
	THE REPAIRER W	/AS TOLD TO PREPARE THE ES	TIMATE.			