

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN201330709H

ARULCHELVAN S • RUTHRA RAM • DON TAN

Our ref: AS.220822.kc

Your ref: To be advised

17 November 2022

LIBERTY INSURANCE PTE LTD
51 CLUB STREET
SINGAPORE 069428

BY EMAIL / PDX

Dear Sirs,

**ACCIDENT INVOLVING FBL 7633R & SMN 7098U ALONG TANJONG PAGAR ROAD
ON 30 AUGUST 2022**

We were instructed by the abovenamed to claim damages against you in connection with a road traffic accident on 30 August 2022 along Tanjong Pagar Road involving motor cycle FBL 7633R and your vehicle SMN 7098U driven by your authorised driver, servant and/or agent.

We are instructed that the accident was caused by your insured's negligent driving and/or management of your vehicle. As a result of the accident, our **client's vehicle was damaged**. She has been put to loss and expense, particulars of which are as follows:

a)	cost of repair	S\$ 16,800.00
b)	loss of use (10 days x \$50.00)	S\$ 500.00
c)	Survey Report	S\$ 868.00
d)	Legal Fees (+GST)	S\$ <u>1,070.00</u>
	TOTAL	S\$ <u>19,238.00</u>

A copy of the traffic police report, traffic police investigation outcome, final repair bill, survey report and photographs are enclosed for your reference.

Please note that if you are insured and wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send us an acknowledgement of the receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the above accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

If your insurer wishes to conduct a post repair inspection of our client's vehicle not conducted previously, your insurer is required to make the request to us within **seven (7) days** of receipt of this letter of claim.

Yours faithfully,



MR ARULCHELVAN S

Enclosure(s)



**SINGAPORE
POLICE FORCE**



T/20220831/7038

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20220831/7038

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/08/2022 15:50	Video Report No.:	Station Diary No.:
--	-------------------	--------------------

Informant's Particulars			
Name of Informant: OH SHI JIA		Address: 784 YISHUN AVENUE 2 #08-1523 SINGAPORE 760784	
ID Type / ID No.: NRIC NO / S9345348D		Contact No.: Home/Office: Mobile: 83885194	
Nationality: SINGAPORE CITIZEN		Email: SHIJIAOH@GMAIL.COM	
Sex: Female	Age: 28	Date of Birth: 28/11/1993	Type of Informant: Rider
Race: Chinese		Language: English	Institution / School Name:
Occupation:		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 30/08/2022 09:00	Type of Location: Straight Road
Location: TANJONG PAGAR ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of
FBL7633R	Motorcycle	YAMAHA	YZF-R1	Yellow		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBL7633R	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/01019699	06/03/2022	05/03/2023



**SINGAPORE
POLICE FORCE**



T/20220831/7038

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20220831/7038

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	OH SHI JIA	ID No.	S9345348D
Related Vehicle	FBL7633R (Motorcycle)	Contact No.	83885194
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	30/08/2022	Date	30/08/2022
No. of Days granted Medical Leave	03	Degree of	Serious

Brief Details.

At around 9:00AM on 30/08/2022, I was riding my motorcycle bearing vehicle registration number FBL7663R along Tanjong Pagar Road on the right lane. The traffic was clear. I noticed a car ahead bearing vehicle registration number SMN7098U that was stationary on the left lane. I reduced my speed as I was approaching the vehicle. As I was about to pass the vehicle, he suddenly made an abrupt right turn from his stationary position seemingly to perform an illegal U turn. The car served into my lane and collided into me. The impact caused me and my motorcycle to be thrown onto the opposite oncoming lane. I laid in shock on the road and was unable to move my body. I felt pain in my neck, shoulder, back, legs and arms. There were a few passerby and witnesses (MR. ALVIN KHUA, HP NO.: 87489153 / DARREN SABOM, HP NO.: 81273969) to the incident whom also attended to me and contacted the police. The driver did not attend me. Police and ambulance arrived on the scene and I was conveyed by the ambulance to SGH. I was given 3 days hospital leave for my injuries and will be due for a review.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20220831/7038

3 of 3

Report No. T/20220831/7038

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
VILTON HIA WEE SIANG
Contact No.: 65476232

NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.


Date/Time:
31/08/2022 15:50

Classification Of Case:

CO REG NO.: 201912500Z
25 KAKI BUKIT ROAD 4 #01-28
SYNERGY@KB
SINGAPORE 417800
CONTACT: 91469264

INVOICE NO. : BAT20221110-01
DATE : 10/11/2022
REGN NO. : FBL7633R

S/N	DESCRIPTION	QTY	UNIT	AMOUNT
1	LUMP SUM REPAIR	1	\$16,800.00	\$16,800.00
TOTAL :			\$16,800.00	
DEPOSIT :			\$0.00	
AMOUNT DUE :			\$16,800.00	


BIKES AND TEA PTE. LTD

RECEIVED BY

All cheque should be made payable to "BIKES AND TEA PTE. LTD."
All cheque received are subjected to clearance.

THANK YOU FOR YOUR BUSINESS!

Should you have any enquiries concerning

Should you have any enquiries concerning this invoice, please contact us at +65 9146 9264"

APPENDIX G (Supreme Court Practice Directions)

Para. 99B

GUIDELINES FOR PARTY-AND-PARTY COSTS AWARDS IN THE SUPREME COURT OF SINGAPORE

*Pg 5

- I. Use of the Costs Guidelines
1. This Appendix provides guidelines for party-and-party costs in the Supreme Court (the "Costs Guidelines").
2. These Costs Guidelines have been approved for publication by the Judges of the Supreme Court. It is intended to provide a general indication on the quantum and methodology of party-and-party costs awards in specified types of proceedings in the Supreme Court, taking into account past awards made, internal practices and general feedback.
3. The precise amount of costs awarded remains at the discretion of the judicial officer making the award, who may depart from the amounts set out in these Costs Guidelines depending on the particular circumstances of each case (see in particular Order 59, Appendix 1 of the Rules of Court). Nothing in these Costs Guidelines is intended to guide or influence the charging of solicitor-and-client costs.
4. Litigants in person should take note of Order 59, Rule 18A of the Rules of Court, the application of which shall remain unaffected by these Costs Guidelines.
5. It should further be noted that in the event of an appeal, costs awards made by the court of first instance may be supplemented or otherwise modified by the appellate court as appropriate.
6. The Supreme Court may from time to time review these Costs Guidelines.

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE (510607)
BUSINESS REGN. No. 53193457L
Email: willybjt@gmail.com / Mobile: 96699986

INVOICE

Mr. Oh Shi Jia
Block 784 Yishun Avenue 2 #08-1523
HDB Khatib Vale
Singapore 760784

Invoice No : PA/2211/0007/tpw
Our Ref : PA/FBL7633/0922/tpw
Date : 10 November 2022

Claim Type	Third Party	Date of Accident	30 August 2022
Vehicle No.	FBL 7633 R	Date of Inspection	05 September 2022
No	Description	Amount (S\$)	
1	Survey fees inclusive of Transportation and Photographs (68) copies	\$868.00	
	Total	\$868.00	
Singapore Dollar: Eight Hundred and Sixty-Eight Only			
Terms of Payment - Within 30 (Thirty) days after receiving our Final Report & Invoice Payment payable as follows and kindly indicate Invoice No. <ul style="list-style-type: none">• Cheque - Payable to Prudent Adjustors Services• Bank Transfer - DBS 025-902513-4• Paynow - UEN No 53193457LBJT			


Prudent Adjustors Services
Bok Jee Tan

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE 510607
BUSINESS REGN. No. 53193457L
Email: willybit@gmail.com / Mobile: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Ms. Oh Shi Jia
Block 784 Yishun Avenue 2 #08-1523
HDB Khatib Vale
Singapore 760784

Our Ref : PA/FBL7633/0922/tpw
Date : 10 November 2022

REFERENCES

Claim Type	: Third Party	Date of Accident	: 30 August 2022
Vehicle No	: FBL 7633 R	Date of Assignment	: 05 September 2022
Make	: Yamaha	Date of Inspection	: 05 September 2022
Model	: YZF-R1	Date of Re-inspection	: 10 Sept & 25 Oct 2022
Registration Date	: 06 March 2017	COE Expiry	: 05 March 2027
Color	: Yellow	Chassis No	: JYARN321000005631
Odometer	: 46,728km	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Bridgestone	120/70-17	6mm
Rear	Bridgestone	190/55-17	8mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and right sides.
Please refer to photographs and assessment of repairs for details
Enclosed (68) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$22,117.41 Revised Assessment : \$16,800.00 Lump sum

Survey conducted at Revology Bikes Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Eight (8) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBL 7633 R

Our Ref: PA/FBL7633/0922/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

<u>S/N</u>	<u>Description Material</u>	<u>Qty</u>	<u>Condition</u>	<u>Original Quotation</u>	<u>Revised Quotation</u>
1	Windscreen	1 pc	Serviceable	158.80	~
2	Front body upper	1 pc	Cracked	780.80	780.80
3	Front body upper inner panel	1 pc	Cracked	210.40	210.40
4	Rear view Mirror with signal @ \$420.90/-	1 set	Cut	841.80	841.80
5	Handler Bar @ \$171.40/-	2 pcs	Bent RH	342.80	171.40
6	Head lamp assy	1 pc	Cracked	1,736.70	1,736.70
7	Pilot light assy @ \$461.50/-	2 pcs	Hdr cracked	923.00	923.00
8	Front fork assy @ \$1995.60/-	2 pcs	Bent/twisted	3,991.20	3,991.20
9	Steering stem	1 pc	Distorted	820.00	820.00
10	Front fender inner panel	1 pc	Cut	105.80	105.80
11	Front cast wheel	1 pc	Dented	2,131.40	2,131.40
12	Front brake disc @ \$510/-	2 pcs	Warped	1,020.00	1,020.00
13	Front cast wheel axle	1 pc	Bent	251.70	251.70
14	Fuel tank front top cover	1 pc	Hdr cracked	273.30	273.30
15	Side panel assembly @ \$632.30/-	2 pcs	Cut/Hdr cracked	1,264.60	1,264.60
16	Side inner panel @ \$124.50/-	2 pcs	Hdr cracked	249.00	249.00
17	Front footrest @ \$128.50/-	2 pcs	Broken RH	257.00	128.50
18	Front footrest bracket RH	1 pc	Bent	223.60	223.60
19	Tail side cover @ \$328.90/-	2 pcs	Hdr cracked	657.80	657.80
20	Exhaust silencer assy	1 pc	Dented	2,410.20	2,410.20
				18,649.90	18,191.20
List price less discount 10%				1,864.99	1,819.12
				16,784.91	16,372.08
<u>Special nett item</u>					
21	Front fender (carbon fiber)	1 pc	Cut/cracked	623.50	623.50
22	Fuel tank side cover (carbon fiber)	1 set	Cracked	387.20	387.20
23	Engine crankcase protection cover (GB Racing)	1 set	Cut	398.50	398.50
24	Steering cone & bearing	1 set	Necessary	220.00	110.00
25	Exhaust heat shield (carbon fiber)	1 pc	Cracked	332.90	332.90
26	Exhaust muffler guard (carbon fiber)	1 pc	Cracked	465.30	465.30
27	Exhaust pipe gasket	1 pc	Necessary	28.30	28.30
28	Exhaust pipe stopper ring	1 pc	Necessary	65.30	65.30
29	Muffler band	1 pc	Necessary	101.50	101.50
30	Front wheel bearing	1 pc	Necessary	180.00	90.00
31	Fairing slider	1 set	Cut	350.00	280.00
				3,152.50	2,882.50

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBL 7633 R**

Our Ref: PA/FBL7633/0922/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Labour charges

Fuel tank cover respray	450.00	350.00
Remove & re-install camera	280.00	250.00
Body frame repair & align	650.00	550.00
Labour for remove & replace damage parts	800.00	600.00
	<hr/>	<hr/>
	2,180.00	1,750.00

Total parts & labour concluded	<u>22,117.41</u>	<u>21,004.58</u>
--------------------------------	------------------	------------------

Lump sum repair adjustment		<u>16,800.00</u>
----------------------------	--	-------------------------

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.



Prudent Adjustors Services
Bok Jee Tan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 348D

Vehicle Details

Vehicle No.: FBL7633R
Vehicle to be Exported: Yes
Intended Deregistration Date: 06 Sep 2022
Vehicle Make: YAMAHA
Vehicle Model: YZF-R1
Primary Colour: Yellow
Manufacturing Year: 2016
Engine No.: N526E009050
Chassis No.: JYARN321000005631
Maximum Power Output: -
Open Market Value: \$20,393.00
Original Registration Date: 06 Mar 2017
First Registration Date: 06 Mar 2017
Transfer Count: 2
Actual ARF Paid: \$3,059.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 05 Mar 2027
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$6,412.00
COE Rebate Amount: \$2,882.00
Total Rebate Amount: \$2,882.00

The information contained herein is correct as at 06 Sep 2022

OK

Advertisement

Motorcycles > Motorcycles for Sale > Class 2 > Yamaha



Share

402 likes

Report

carousell

Electronics

Fashion

Luxury

Services

Cars

Hello, Jee Tan



Sell

Search for anything

All of Singapore

Search

S\$36,000

ra Oscar Charlie @namelessv...

5.0 (42 reviews)

Used

Meetup

Edgedale Plains

Chat

Description

Bumped

Make

Type

4 days ago

Yamaha

Sports Bike

Non urgent sale

COE sept 2027

Will only sell if the price is right

2016 model

reg sept 2017

Mileage 75k ongoing

Major Wear and Tear replaced

Write a custom message...

Send message to @namelessvg

By continuing, you agree to our [Terms of Service](#)
[Privacy Policy](#).

S\$ 36000

Make Offer



Advertisement


read more



Meet-up



Edgedale Plains

Privacy • Terms




























































Re-Survey








Re-Survey









Re-Survey









Re-Survey








Re-Survey







Re-Survey







Re-Survey






Re-Survey







Re-Survey








Re-Survey






Re-Survey






Re-Survey





Re-Survey
After Repair






Re-Survey
After Repair








Re-Survey
After Repair






Re-Survey
After Repair





Re-Survey
After Repair





**SINGAPORE
POLICE FORCE**
SAFEGUARDING EVERY DAY

Our Ref: TP/IP/22876/2022

OH SHI JIA
784 YISHUN AVENUE 2
#08-1523
Singapore 760784

Traffic Police
10 Ubi Avenue 3
Singapore 408865

IB Call Centre: 65470000
FAX: 65474883

Date: 18/10/2022

Dear Mdm

**TRAFFIC ACCIDENT INVOLVING FBL7633R & SMN7098U ALONG TANJONG PAGAR ROAD
TOWARDS KEPPEL ROAD ON 30/08/2022 AT 08:57 HRS**

I refer to the above accident.

2 We have completed our investigation into the case. Action has been initiated against the driver of SMN7098U for the offence of **CARELESS DRIVING WITHOUT REASONABLE CONSIDERATION CAUSING HURT UNDER SECTION 65(1)(b) PUNISHABLE UNDER SECTION 65(4)(a) OF THE ROAD TRAFFIC ACT, 1961.**

3 Please be informed that our decision does not preclude you from pursuing insurance / civil claims.

4 If you have any clarification, you may contact the Investigation Officer, Ahmad Syafiq Bin Harris at office number: 65476331.

Yours faithfully,
Sr Staff Sgt Ahmad Syafiq Bin Harris
Investigation Officer (GIT D)
Traffic Police
Singapore Police Force

This is a computer-generated letter. No signature is required.

A FORCE FOR THE NATION