



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/LPC23004538/Rqy3-1

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS3/LPC23004538/Rqy3~~  
Date: ~~04/05/2023~~ 19/07/2023  
Code: LPC2

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

|              |            |                |                                  |
|--------------|------------|----------------|----------------------------------|
| Insured Veh. | GBB 2407M  | Veh. Inspected | XD 4695M                         |
| Policy No.   |            | Coverage (\$)  | 0.00                             |
| Claim No.    |            | Excess (\$)    | 0.00                             |
| Assign From  | GERALD POH | Assign Date    | <del>04/05/2023</del> 19/07/2023 |

### 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

### 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

### 4. Description of Damages

|  |  |
|--|--|
|  |  |
|--|--|

### 5. General Information

|                |                                                                                               |                 |            |
|----------------|-----------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 01/05/2023                                                                                    | Inspection Date | 04/05/2023 |
| Survey held at | REDANTS ENGINEERING<br>10 Buroh Street<br>#04-26/29 West Connect Building<br>Singapore 627564 |                 |            |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.