



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/SMO23002123/Uqy3-1

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE #03-03  
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: ~~CS/SMO23002123/Uqy3~~  
Date: ~~27/02/2023~~ 19/07/2023  
Code: SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 8105B	Veh. Inspected	SLE 8935G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2300781/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	<del>27/02/2023</del> 19/07/2023

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	21/02/2023	Inspection Date	27/02/2023
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.