



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD			Ref: CS/HSB23007352/Uvp3	
10 MARINA BOULEVARD			Date: 20/07/2023	
#48-01 MARINA BAY FINANCIAL CENTRE TOWER				
2SINGAPORE 018983			Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 3252U	Veh. Inspected	SLH 9508J
	Policy No.		Coverage (\$)	0.00
	Claim No.	S3M04O94	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	20/07/2023
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	18/07/2023	Inspection Date	20/07/2023
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			